



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR21005143/Guf3e2 Date: 30/04/2021 Code: SMR		
1. Policy Particulars :- (THIRD PARTY CLAIM)					
Insured Veh.		SHB 5893B	Veh. Inspected		FBR 8944E
Policy No.			Coverage (\$)		0.00
Claim No.		TAX/04/21/2027	Excess (\$)		0.00
Assign From		HUA YEN	Assign Date		26/04/2021
2. Vehicle Particulars & Condition					
Make & Model		YAMAHA MX KING T150	c.c		150
Engine No.		HIDDEN	Year of Reg.		2020
Chassis No.		MH3UG0750LK072816	Colour		BLUE
Odometer		-	Steering		IN ORDER
Brakes		IN ORDER	Modification		NIL
General		GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	90/80-17	DUNLOP	4 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	120/70-17	DUNLOP	4 mm	
	L/H Rear Tyre			mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND REAR PORTION.				
5. General Information					
	Accident Date	10/04/2021	Inspect Date / Time 26/04/2021 (04:00 PM)		
	Survey held at	EQUATOR BROTHERHOOD 25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800			
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

Report Ref No. CS3/SMR21005143/Guf3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.