

ASS. REC. BY:

REF:

AIG/

CS/AIG21005146/Kqf3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

0999993650

Claims No.

6473742384SG

Sum Insured:

Excess:


1900

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$ 70k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12 days

Res.: Yes or No

Lum Sum:

1.8.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

CBBG 8355B

Yr Regn:

09, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

M. Vito 114 cc 2143

Colour:

White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

92925

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WOF 44760 32 3339042

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Mod:

Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

205/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Royal

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

12/4/21

D.O.I.

26/4/2021

Survey held at

Des. of Damages:

Frt / Rear / O/S / N/S / U/C / Rooftop or

& / R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/04/21 @ 4.29pm revert to AIG via Merimen.

27/04/21 @ 5.23pm Kok Chong informed C/A via Merimen.

27/04/21 @ 5.53pm Informed Candy C/A & ex: \$1900 by email.

Kenneth confirmed final fig \$20970.15, 12 days. (Red \$4654.50, 18%)

Date/Time, File Pass to?



: Prell. Report

1) 05/07 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

12

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S - RS - SI

Parties

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

MER-OD

Lump Sum / I.B.I. (\$

20970.15



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE :

ACCIDENT DATE : 12/04/2021

ESTIMATE

NO : QUOT202104-000032(00)

DATE : 26/04/2021

POLICY NO : 999995580

VEH REG NO : GBG6355B

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323339042

ENGINE NO : 65195034218196

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG6355B

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Rear windscreen glass	1	620.00	620.00
2 Tailgate	1	1,450.00	1,450.00
3 Tailgate absorber - RH / LH	2	78.00	156.00
4 Tailgate hinges - RH / LH	2	115.00	230.00
5 Tailgate lock	1	195.00	195.00
6 Tailgate weatherstrip	1	180.00	180.00
7 Tailgate centre trim	1	28.00	28.00
8 Tailgate centre trim rivets	5	5.50	27.50
9 Tailgate inner handle strip	1	28.00	28.00
10 Tailgate inner trimboard	1	48.00	48.00
11 Tailgate trimboard clips	15	5.50	82.50
12 Tailgate centre logo	1	48.00	48.00
13 Tailgate 'VITO' emblem	1	52.00	52.00
14 Tailgate '114 CDI' emblem	1	62.00	62.00
15 Tailgate 'C & C' emblem	1	38.00	38.00
16 Tailgate wiper motor	1	310.00	310.00
17 Tailgate wiper motor cover	1	75.00	75.00
18 Tailgate wiper blade	1	48.00	48.00
19 Tailgate wiper arm	1	98.00	98.00
20 Tailgate wiper cap	1	12.00	12.00
21 Rear end panel (outer)	1	252.00	252.00
22 Rear end panel (inner)	1	285.00	285.00
23 Rear bumper	1	980.00	980.00
24 Rear bumper reinforcement	1	135.00	135.00
25 Rear bumper retainer - LH / RH	2	65.00	130.00
26 Rear bumper reflector - RH / LH	2	55.00	110.00
27 Rear bumper sensor cable	1	115.00	115.00
28 Rear bumper reverse sensor	3	135.00	540.00
29 Rear bumper sensor seals	4	8.00	32.00
30 Rear bumper clips	15	5.50	82.50
31 Taillamp assy - RH / LH	2	550.00	1,100.00
32 Taillamp assy lower garnish - RH / LH	2	98.00	196.00
33 Bonnet	1	850.00	850.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE :
ACCIDENT DATE : 12/04/2021

PAGE: 2

ESTIMATE

NO : QUOT202104-000032(00)
DATE : 26/04/2021
POLICY NO : 999995580
VEH REG NO : GBG6355B
MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR
CHASSIS NO : WDF44760323339042
ENGINE NO : 65195034218196
REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG6355B

Description	Quantity	Unit Price	Amount
34 Headlamp assy - LH	1	CM 1,850.00	1,850.00 ✓
35 Front bumper	1	RM 780.00	780.00 ✓
36 Front bumper reinforcement	1	480.00	480.00 7
37 Front bumper carrier -- LH	1	75.00	75.00 7
38 Front bumper side retainer - LH	1	58.00	58.00 X
39 Front bumper clips	15	6.50	97.50 ✓
			11,936.00
		Add 10%	1,193.60
			13,129.60
SPECIAL NET			
40 Rear windscreen sealant		60.00	60.00 40.00
41 Tailgate "70km/h" sticker		25.00	25.00 12.00
42 Tailgate '6 pax sticker		25.00	25.00 12.50
43 Rear number plate		40.00	40.00 ✓
44 Front number plate		40.00	40.00 ✓
			190.00
LABOUR			
45 To remove and refit rear windscreen glass		150.00	150.00 12.00
46 To transfer damaged tailgate interior mechanism to new tailgate	1	120.00	120.00 6.00
47 To remove and refit front and rear bumper sensor	1	200.00	200.00 12.00
48 To check and rectify wiring system	1	80.00	80.00 4.00
49 To panel beat and straighten rear floorboard panel, front & rear rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,800.00	1,800.00 110.00
50 To putty and spray paint on affected areas (front & rear portion)	1	1,800.00	1,800.00 120.00
51 To supply art works & spray barcode on tailgate, RH body panel and bonnet	1 (B:11)	3,500.00	3,500.00 ?
			7,650.00
		TOTAL	S\$ 20,969.60
		ADD GST @ 7%	1,467.87
		GRAND TOTAL	S\$ 22,437.47

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(Interd ??)

SINGAPORE DOLLAR TWENTY-TWO THOUSAND FOUR HUNDRED THIRTY-SEVEN AND CENTS FORTY-SEVEN ONLY

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

778Z

Vehicle Details

Vehicle No.:

GBG6355B

Vehicle to be Exported:

No

Intended Deregistration Date:

26 Apr 2021

Vehicle Make:

MERCEDES BENZ

Vehicle Model:

VITO 114 CDI PANEL VAN LONG AT ABS 5DR

Primary Colour:

White

Manufacturing Year:

2017

Engine No.:

65195034218196

Chassis No.:

WDF44760323339042

Maximum Power Output:

-

Open Market Value:

\$37,836.00

Original Registration Date:

18 Sep 2017

First Registration Date:

18 Sep 2017

Transfer Count:

0

Actual ARF Paid:

\$1,892.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

17 Sep 2027

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$36,879.00

COE Rebate Amount:

\$23,580.00

Total Rebate Amount:

\$23,580.00

The information contained herein is correct as at 26 Apr 2021

OK



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/04/2021 21:19 (SGT)
Date of Accident	12/04/2021 16:10 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE (Tuas)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG6355B
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD
Company Reg No	1XXXXX778Z
Email Address	azrin.bejaramin@daimler.com
Mobile Phone No	(Phone) +65-90231717
Alternative Phone No	(Office) +65-90231717

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	VITO 114 CDI PANEL VAN LONG AT ABS 5DR
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	2143


INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	999995580
Cover Note Number	NA

DRIVER

Name of Driver	LIM TIAN ENG
NRIC No	SXXXX812D





Vehicle A: GGG6355B
 Vehicle B: GGG8279A
 Vehicle C: SMK 8410K
 Vehicle D: YP3250U
 Vehicle E: GW4307K
 Vehicle F: SMY4015X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

VERIFY BY AJAX MARS (ARC)
 REPORTING OFFICER
 MOHAMED SAIFULLAH S/O SYED MASOOD

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.: