



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE :

ACCIDENT DATE : 12/04/2021

ESTIMATE

NO : QUOT202104-000032(00)

DATE : 26/04/2021

POLICY NO : 999995580

VEH REG NO : GBG6355B

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323339042

ENGINE NO : 65195034218196

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG6355B

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Rear windscreen glass	1 <i>Shatter</i>	620.00	620.00 <i>L</i>
2 Tailgate	1 <i>B</i>	1,450.00	1,450.00 <i>✓</i>
3 Tailgate-absorber - RH / LH	2 <i>Sn</i>	78.00	156.00 <i>X</i>
4 Tailgate-hinges - RH / LH	2 <i>R</i>	115.00	230.00 <i>X</i>
5 Tailgate lock	1 <i>Not</i>	195.00	195.00 <i>✓</i>
6 Tailgate weatherstrip	1 <i>Wt</i>	180.00	180.00 <i>✓</i>
7 Tailgate centre trim	1 <i>CRM</i>	28.00	28.00 <i>✓</i>
8 Tailgate centre trim rivets	5 <i>Na</i>	5.50 <i>20SN</i>	27.50 <i>✓</i>
9 Tailgate-inner-handle-strip	1 <i>Sn</i>	28.00	28.00 <i>X</i>
10 Tailgate inner trimboard	1 <i>CRM</i>	48.00	48.00 <i>✓</i>
11 Tailgate trimboard clips	15 <i>Na</i>	5.50 <i>50SN</i>	82.50 <i>✓</i>
12 Tailgate centre logo	1 <i>Na</i>	48.00	48.00 <i>✓</i>
13 Tailgate 'VITO' emblem	1 <i>Na</i>	52.00	52.00 <i>✓</i>
14 Tailgate '114 CDI' emblem	1 <i>Na</i>	62.00	62.00 <i>✓</i>
15 Tailgate 'C & C' emblem	1 <i>Na</i>	38.00	38.00 <i>✓</i>
16 Tailgate wiper motor	1 <i>Mf CM</i>	310.00	310.00 <i>✓</i>
17 Tailgate wiper motor cover	1	75.00	75.00 <i>✓</i>
18 Tailgate wiper blade	1 <i>Sn</i>	48.00	48.00 <i>X</i>
19 Tailgate wiper arm	1	98.00	98.00 <i>✓</i>
20 Tailgate wiper cap	1 <i>Sn</i>	12.00	12.00 <i>X</i>
21 Rear end panel (outer)	1 <i>B</i>	252.00	252.00 <i>✓</i>
22 Rear end panel (inner)	1 <i>B</i>	285.00	285.00 <i>✓</i>
23 Rear bumper	1 <i>Bu</i>	980.00	980.00 <i>✓</i>
24 Rear bumper reinforcement	1 <i>CRM / DIT</i>	135.00	135.00 <i>✓</i>
25 Rear bumper retainer - LH / RH	2 <i>DIT</i>	65.00	130.00 <i>✓</i>
26 Rear bumper reflector - RH / LH	<i>Als Bro</i> 2 <i>1</i>	55.00 <i>✓</i>	110.00 <i>✓</i>
27 Rear bumper sensor cable	1 <i>Tn</i>	115.00	115.00 <i>✓</i>
28 Rear bumper reverse sensor	3 <i>4</i> <i>Sho</i>	135.00 <i>40S</i>	540.00 <i>444</i>
29 Rear bumper sensor seals	4 <i>Na</i>	8.00	32.00 <i>✓</i>
30 Rear bumper clips	15 <i>Na</i>	5.50 <i>50SN</i>	82.50 <i>✓</i>
31 Taillamp assy - RH / LH	2 <i>CRM</i>	550.00	1,100.00 <i>✓</i>
32 Taillamp assy lower garnish - RH / LH	2 <i>Not DIT</i>	98.00	196.00 <i>✓</i>
33 Bonnet	1 <i>R</i>	850.00	850.00 <i>X</i>

6716



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE :

ACCIDENT DATE : 12/04/2021

ESTIMATE

NO : QUOT202104-000032(00)

DATE : 26/04/2021

POLICY NO : 999995580

VEH REG NO : GBG6355B

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF4476032339042

ENGINE NO : 65195034218196

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG6355B

Description	Quantity	Unit Price	Amount
		S\$	S\$
✓ 34 Headlamp assy - LH	1	CRA 1,850.00	1,850.00 ✓
35 Front bumper	1	B 780.00	780.00 ✓
36 Front bumper reinforcement	1	Bent 480.00	480.00 7✓
37 Front bumper carrier -- LH	1	Cra 75.00	75.00 7✓
38 Front bumper-side retainer -- LH	1	58.00	58.00 X
39 Front bumper clips	15	SUSN 6.50	97.50 ✓
			11,936.00 318
			Add 10% 1,193.60
			13,129.60
SPECIAL NET			
40 Rear windscreen sealant	1	M 60.00	60.00 40JN
41 Tailgate "70km/h" sticker	1	25.00	25.00 12Vn
42 Tailgate '6 pax sticker	1	25.00	25.00 12Sn
43 Rear number plate	1	40.00	40.00 ✓
44 Front number plate	1	40.00	40.00 ✓
			190.00 314
LABOUR			
45 To remove and refit rear windscreen glass	1	150.00	150.00 1201
46 To transfer damaged tailgate interior mechanism to new tailgate	1	120.00	120.00 601
47 To remove and refit front and rear bumper sensor	1	200.00	200.00 1201
48 To check and rectify wiring system	1	80.00	80.00 401
49 To panel beat and straighten rear floorboard panel, front & rear rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,800.00	1,800.00 11001
50 To putty and spray paint on affected areas (front & rear portion)	1	1,800.00	1,800.00 12001
51 To supply art works & spray barcode on tailgate, RH body panel and bonnet	1	(Bill) 3,500.00	2800,500.00 ?
			7,650.00 5440
TOTAL			S\$ 20,969.60
ADD GST @ 7%			1,467.87
GRAND TOTAL			S\$ 22,437.47

SINGAPORE DOLLAR TWENTY-TWO THOUSAND FOUR HUNDRED THIRTY-SEVEN AND CENTS FORTY-SEVEN ONLY



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 3

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE :

ACCIDENT DATE : 12/04/2021

ESTIMATE

NO : QUOT202104-000032(00)

DATE : 26/04/2021

POLICY NO : 999995580

VEH REG NO : GBG6355B

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323339042

ENGINE NO : 65195034218196

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG6355B

Description	Quantity	Unit Price	Amount
		S\$	S\$

parts : \$ 10,891.10

SN : \$ 314.00

Labour : \$ 5,440.00

supp : \$ 4,325.05

\$ 20,970.15

XS 1,900.00

\$ 19,070.15

7% 1,334.91

\$ 20,405.06

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE :

ACCIDENT DATE : 12/04/2021

ESTIMATE

NO : QUOT202104-000032(00)

DATE : 17/05/2021

POLICY NO : 999995580

VEH REG NO : GBG6355B

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323339042

ENGINE NO : 65195034218196

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG6355B

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Front safety belt -- RH / LH	2	589.42	1,178.84
2 Front safety belt -- centre	1	589.48	589.48
3 Airbag control unit	1	1,196.00	1,196.00
4 Rear end panel top garnish	1	98.00	98.00
5 Tail lamp corner pillar - LH	1	120.00	120.00
6 Rear spare tyre holder	1	295.00	295.00
			3,477.32
		Add 10%	347.73
			3,825.05
LABOUR			
7 TTo remove and refit front safety belt and airbag control unit	1	480.00	480.00
8 To reset and reprogramme airbag module	1	350.00	350.00
			830.00
		TOTAL	S\$ 4,655.05
		ADD GST @ 7%	325.85
		GRAND TOTAL	S\$ 4,980.90

SINGAPORE DOLLAR FOUR THOUSAND NINE HUNDRED EIGHTY AND CENTS NINETY ONLY

4,325.05

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE