

Massive Trading & Auto

Bik 5038 #01405 Ang Mo Kio Industrial Pk 2 Singapore 669541
Hlp 91082728

Fax : 64816131

Cheah Lean Chye
Bik 5A Marsiling Drive
#14-461 Singapore 732005

Vehicle No : SGD 5900 R
Make/Model : Honda CRV
Year : 2016

*Not Authorized
1 Day 838000
Returning After Point
5 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy
1 pc	Rear tail-gate inner lock
1 pc	Rear tail-gate inner lock switch
1 pc	Rear tail-gate outer handle
1 pc	Rear tail-gate emblem "H"
1 pc	Rear tail-gate emblem "CRV"
1 pc	Rear tail-gate lower outer garnish
1 pc	Rear tail-gate inner trim board
2 pcs	Rear tail-lamp assy
2 pcs	Rear fender inner trim board
2 pcs	Rear fender arch protector
1 pc	Rear bumper
2 pcs	Rear side bumper
2 pcs	Rear bumper reflector
2 pcs	Rear bumper side retainer
1 pc	Rear boot rubber
1 pc	Rear end panel
1 pc	Rear end panel inner garnish
1 pc	Rear spare tyre panel
1 pc	Rear spare tyre top board
1 pc	Rear exhaust silencer box
2 pcs	Rear reverse sensor
1 pc	Rear buzzer

My	\$1,040.60	✓
Ne	\$203.60	✓
Ne	\$158.80	✓
My	\$305.90	✓
Ne	\$40.10	✓
Ne	\$55.70	✓
Ne	\$454.60	✓
My	\$240.60	✓
Ne	\$1,100.20	✓
Ne	\$567.80	✓
Ne	\$283.90	✓
Ne	\$145.10	✓
Ne	\$290.20	✓
Ne	\$594.30	✓
My	\$371.00	✓
Ne	\$96.20	✓
Ne	\$111.80	✓
Ne	\$185.70	✓
Ne	\$531.20	✓
Ne	\$109.70	✓
Ne	\$1,133.40	✓
Ne	\$572.10	✓
Ne	\$955.70	✓
Ne	\$574.20	✓
Ne	\$155.20	✓
Ne	\$9,983.60	✓
Less 20 %	\$1,996.72	
	\$7,986.88	

short

\$287.10	✓
\$574.20	✓
\$155.20	✓
\$9,983.60	✓
\$1,996.72	✓
\$7,986.88	✓

S Nett Item

1 pc	Rear no plate
1 pc	Rear windscreen sealant
20 pcs	Clip

\$2.00	✓
\$40.00	✓
\$40.00	✓
\$40.00	✓
\$120.00	✓
balance c/f	\$8,106.88

ASS. REC. BY: _____

REF: _____

SGD 5900 R

balance b/f

\$8,106.88

Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting.

To putty and spray paint

Check & reconnect wiring.

To respray anti-rust proofing treatment

Remove/refit rear tail-gate glass to new door

Remove/renew rear tail-gate mechanism, trim board, wiper motor to new door

Remove/refit rear upholstery to facilitate repair.

Remove/renew rear exhaust silencer

\$1,500.00

\$1,300.00

\$45.00

\$150.00

\$120.00

\$100.00

\$150.00

nn \$120.00 X

\$11,591.88

Total

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____