

VEHICLE DETAIL

Vehicle No	QX 1697 E	SCDF Ref. No.	ACC-IND-21-12
Date Booked In			

REPAIR DESCRIPTIONS



- 1) Remove & replace wind screen (pic 1)
- 2) Remove & replace wind screen moulding (pic 1)
- 3) Replace wind screen wiper sensor (pic 1)
- 4) Water seepage for wind screen (pic 1)
- 5) Remove & replace dented bonnet (pic 2)
- 6) Remove & replace bonnet upper lock (pic 2)
- 7) Remove & replace bonnet lower lock (pic 2)
- 8) Remove & replace bonnet stand (pic 3)
- 9) Remove & replace bonnet hinge (pic 4)
- 10) Remove & replace R/H head lamp (pic 5)
- 11) Remove & replace R/H fender inner panel (pic 6)
- 12) Replace R/H dislodged fender (pic 7)
- 13) Replace R/H fender signal lamp (pic 7)
- 14) Replace R/H rear view mirror garnish (pic 8)
- 15) Replace R/H blind spot mirror (pic 9)
- 16) Replace R/H dislodged fender garnish (pic 10)
- 17) Remove & replace AP panel (pic 11)
- 18) Remove & replace radiator grill (pic 12)
- 19) Remove & replace head lamp support (pic 13)
- 20) Remove & replace front bumper (pic 14)
- 21) Replace front bumper retainer (pic 14)
- 22) Replace front bumper step board (pic 14,15)
- 23) Replace front bumper sensor (pic 15)
- 24) Remove & replace front bumper support (pic 16)
- 25) Remove & replace R/H bumper strobe light (pic 17)
- 26) Remove & replace R/H fog lamp (pic 18)
- 27) Replace front number plate & casing (pic 19)
- 28) Remove & replace R/H mud flap (pic 20)
- 29) Remove & replace air con motor fan (pic 21)
- 30) Remove & replace radiator (pic 22)
- 31) Remove & replace radiator top & bottom hose (pic 22)
- 32) Remove & replace air con condenser (pic 23)
- 33) Remove & replace dented power steering pipe (pic 24)
- 34) Remove & replace radiator garnish (pic 25,26)
- 35) Remove & replace air cleaner housing (pic 27)
- 36) Remove & replace ABS wire harness (pic 28)
- 37) Remove & replace engine mounting
- 38) Remove & replace gear box mounting
- 39) Panel beat dented ABS mounting plate (pic 29)
- 40) Panel beat R/H dented fender garnish panel (pic 30)
- 41) Cut & weld dented bumper strobe light bracket (pic 31)
- 42) Wiring for all lighting (pic 5,7,15,17,18 & 28)
- 43) Replace bonnet sticker & wording (pic 2)
- 44) Putty & spray paint bonnet (pic 2)
- 45) Spray lacquer over after putting up sticker & wording for bonnet (pic 2)

- 46) Replace R/H fender sticker (pic 7)
47) Putty & spray paint R/H fender & AP panel (pic 7,11)

PHOTOS OF DAMAGED PARTS

Wind screen crack (pic 1)	Bonnet dented (pic 2)
	
Bonnet stand dented (pic 3)	Bonnet hinge dented (pic 4)
	
R/H head lamp shattered (pic 5)	R/H fender panel dented (pic 6)
	
R/H fender dislodged (pic 7)	R/H rear view mirror garnish dislodged (pic 8)
	
R/H blind spot mirror dislodged (pic 9)	R/H fender garnish dislodged (pic 10)
	
AP panel dented (pic 11)	Radiator grill dented (pic 12)
	
Head lamp support crack (pic 13)	Front bumper crack (pic 14)

A close-up photograph of the front bumper area. A yellow oval highlights a dislodged sensor. A label 'Head lamp support crack' is visible in the top right corner of the image.	A photograph of the front bumper. A yellow oval highlights a dent in the bumper support.
Front bumper sensor dislodged (pic 15)	Front bumper support dented (pic 16)
A close-up photograph of the right-hand bumper. A yellow oval highlights a crack in the bumper strobe light.	A photograph of the front bumper support. A yellow oval highlights a dent in the support.
R/H bumper strobe light crack (pic 17)	Front bumper support dented (pic 18)
A close-up photograph of the right-hand fog lamp. A yellow oval highlights a crack in the fog lamp.	A close-up photograph of the right-hand fog lamp. A yellow oval highlights a crack in the fog lamp.
R/H fog lamp crack (pic 19)	R/H fog lamp crack (pic 20)
A photograph of the front number plate. A yellow oval highlights the dislodged plate.	A photograph of the front right-hand mud flap. A yellow oval highlights the torn mud flap.
Front number plate dislodged (pic 21)	Front R/H mud flap torn (pic 22)
A photograph of the air conditioning motor fan. A yellow oval highlights a crack in the fan.	A photograph of the radiator. A yellow oval highlights a dent in the radiator.
Air con motor fan crack (pic 23)	Radiator dented (pic 24)
A photograph of the air conditioning condenser. A yellow oval highlights a dent in the condenser.	A photograph of the power steering pipe. A yellow oval highlights a dent in the pipe.
Air con condenser dented (pic 25)	Power steering pipe dented (pic 26)
A photograph of the radiator garnish. A yellow oval highlights a tear in the garnish.	A photograph of the radiator garnish. A yellow oval highlights a tear in the garnish.
Radiator garnish torn (pic 27)	Radiator garnish torn (pic 28)
A photograph of the air cleaner housing. A yellow oval highlights a crack in the housing.	A photograph of the ABS wire. A yellow oval highlights a tear in the wire.
Air cleaner housing crack (pic 29)	ABS wire hardness torn (pic 30)

	
ABS mounting plate dented (pic 29)	R/H fender garnish panel dented (pic 30)
	
Bumper strobe light bracket dented (pic 31)	QX 1697 E
	