



TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : GBF8043T

Date of Accident : 23 April 2021

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Fones Gordon

Date : 26 April 2021

Estimate To Repair SKT8526L - Toyota Corolla Altis Classic 1.6 CVT

Chassis No : MR053REH104534841

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear bumper <i>Dis</i>	\$ 486.50
02	8 ps	rear bumper clips @ \$4.30 <i>all</i>	\$ 34.40
03	1 pc	o/s rear bumper reflector <i>570</i>	\$ 58.00
04	1 pc	rear bumper parking sensor holder <i>17</i>	\$ 35.00
05	2 ps	rear bumper side retainer @ \$120.00 <i>o/s one</i>	\$ 240.00
06	2 ps	rear bumper bracket @ \$68.00 <i>17</i>	\$ 136.00
07	1 pc	rear bumper beam <i>sent</i>	\$ 395.00
08	1 pc	rear bootlid <i>20/3uc</i>	\$ 755.00
09	2 ps	rear bootlid reflector @ \$355.00 <i>5uc</i>	\$ 710.00
10	1 pc	rear bootlid inner trim <i>17</i>	\$ 307.50
11	2 ps	rear bootlid hinge @ \$68.00 <i>17</i>	\$ 136.00
12	1 pc	rear bootlid lock <i>17</i>	\$ 382.50
13	1 pc	rear bootlid Corolla emblem <i>17</i>	\$ 61.00
14	1 pc	rear bootlid Altis emblem <i>17</i>	\$ 48.00
15	1 pc	rear bootlid Toyota logo <i>17</i>	\$ 57.30
16	1 pc	rear bootlid outer chrome moulding <i>17</i>	\$ 233.70
17	1 pc	rear bootlid weatherstrip <i>17</i>	\$ 185.00
18	1 pc	rear bootlid catch <i>17</i>	\$ 26.00
19	2 ps	taillamp @ \$395.00 <i>one</i>	\$ 790.00
20	1 pc	taillamp clips <i>o/s</i>	\$ 4.30
21	1 pc	o/s taillamp panel <i>300.00</i>	\$ 84.00
22	1 pc	rear end panel <i>300.00</i>	\$ 590.00
23	1 pc	rear end panel top garnish <i>17</i>	\$ 240.00
24	1 pc	o/s rear fender <i>Dis</i>	\$ 986.80
25	1 pc	o/s rear fender inner cowlings <i>17</i>	\$ 52.80
26	1 pc	o/s rear fender inner cowlings clips <i>17</i>	\$ 4.30
27	1 pc	o/s rear fender inner trim <i>Dis</i>	\$ 256.00
28	1 pc	o/s rear fender inner garnish <i>17</i>	\$ 759.00
29	1 pc	o/s rear fender inner garnish clips <i>17</i>	\$ 4.30
30	1 pc	o/s rear fender inner panel	\$ 265.00
31	1 pc	o/s rear fender inner tow garnish	\$ 105.00
32	1 pc	o/s rear door <i>300.00</i>	\$ 1,079.60
33	1 pc	o/s rear door lock	\$ 445.00
34	1 pc	o/s rear door outer handle <i>17</i>	\$ 143.00
35	1 pc	o/s rear door outer moulding <i>17</i>	\$ 111.60
36	1 pc	o/s rear door weatherstrip <i>17</i>	\$ 174.60
37	1 pc	o/s rear door power window motor	\$ 585.00
38	1 pc	o/s rear door power window regular	\$ 265.00
39	1 pc	o/s rear door inner trim board	\$ 746.50

*Not Adjust
all
27/4/21*

*1/5
12 days*

take 2 hrs Altis 142

Req. 27/4/2021

391.70 x 2 = 783.40



TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : GBF8043T

Date of Accident : 23 April 2021

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Fones Gordon

Date : 26 April 2021

Estimate To Repair SKT8526L - Toyota Corolla Altis Classic 1.6 CVT

Chassis No : MR053REH104534841

S/No	Quantity	Description	Amount	
		<u>LIST ITEMS</u>		
40	1 pc	n/s rear fender 2	\$ 986.80	X
41	1 pc	n/s rear fender inner trim 17	\$ 759.00	X
42	1 pc	n/s rear fender inner trim clips 17	\$ 4.30	X
43	1 pc	floor panel 2	\$ 797.00	X
44	1 pc	floor board	\$ 267.00	?
45	1 pc	speaker panel	\$ 256.00	?
46	1 pc	speaker board 17	\$ 756.20	X
47	1 pc	rear windscreen panel 25	\$ 658.00	X
48	1 pc	roof lining 17	\$ 1,120.00	X
49	1 pc	rear axle	\$ 2,850.00	?
50	1 pc	o/s rear wheel bearing	\$ 670.00	?
51	1 pc	o/s rear absorber	\$ 200.00	?
52	1 pc	exhaust box	\$ 939.00	?
53	1 pc	rear windscreen glass 5 hooked	\$ 985.90	✓
			\$ 23,227.90	
		Less 25 %	\$ 5,806.98	
			\$ 17,420.93	
		<u>SPECIAL NETT ITEMS</u>		
54	2 ps	rear bumper parking sensor @ \$159.95 17	\$ 319.90	X
55	1 pc	rear windscreen primer 2cc	\$ 30.00	✓
56	1 pc	rear windscreen sealant 2cc	\$ 80.00	40
57	1 pc	rear windscreen inner seal 2cc	\$ 50.00	30
58	1 pc	o/s rear tyre 2P 160 1085/W	\$ 280.00	602
59	1 pc	o/s rear rim 2cc/1cm	\$ 450.00	400
			\$ 1,209.90	
		<u>LABOUR & MISC. CHARGES</u>		
01		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 2,400.00	1600
02		Putty and spray painting of the affected portion.	\$ 1,400.00	1200
03		To remove and refit rear windscreen glass.	\$ 140.00	120
04		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 250.00	80
05		To dismantle and refit rear seat, backrest, trimming, garnish, roof-lining, speaker shelfboard, carpeting and other to enable body work repair.	\$ 120.00	✓
06		To drop petrol tank, hoses to facilitate bodywork repair, final checking and testing.	\$ 17 80.00	X
07		To reinstall of rear bumper parking sensor.	\$ 80.00	50



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GBF8043T

Date of Accident : 23 April 2021

Mr Fones Gordon

Date : 26 April 2021

Estimate To Repair SKT8526L - Toyota Corolla Altis Classic 1.6 CVT
Chassis No : MR053REH104534841

S/No	Quantity	Description	Amount
		<u>LABOUR & MISC. CHARGES</u>	
08		To check electrical lighting concerned.	\$ 80.00
09		To drop rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	\$ 300.00
10		To transfer of o/s rear door fittings and perform water seepage test.	\$ 80.00
11		To rust-proofing of the affected areas.	\$ 250.00
12		To transfer of o/s rear tyre, rim and on wheel balancing.	\$ 80.00
13		To check steering geometry and computer wheel alignment.	\$ 80.00
			\$ 5,340.00
		Total	\$ 23,970.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

s/n - 608
2 - 3500