

Email: ishareauto@gmail.com



DATE : 04.05.21

Acknowledged by Repairer

Signature:

Date:

Xiao Tony

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR SIDE MIRROR LH <i>Damaged</i>	1	\$ 694.20	\$ 694.20
2	FRONT DOOR LH <i>Dented</i>	1	\$ 1,210.30	\$ 1,210.30
3	FRONT DOOR BLACK STICKER LH <i>New</i>	1	\$ 95.60	\$ 95.60
4	FRONT DOOR STOPPER LH <i>New</i>	2	\$ 19.00	\$ 38.00
5	FRONT DOOR HINGE LH <i>New</i>	2	\$ 54.90	\$ 109.80
6	FRONT DOOR WINDOW GLASS LH <i>Cr</i>	1	\$ 429.20	\$ 429.20
7	FRONT DOOR INNER LOCK LH <i>Damaged</i>	1	\$ 394.10	\$ 394.10
8	FRONT DOOR INNER TRIM LH <i>New</i>	1	\$ 797.40	\$ 797.40
9	FRONT DOOR LOCK CATCHER LH <i>New</i>	1	\$ 41.40	\$ 41.40
10	FRONT DOOR WEATHER STRIP LH <i>New</i>	1	\$ 149.80	\$ 149.80
11	FRONT DOOR OUTER STRIP LH <i>Not New</i>	1	\$ 189.70	\$ 189.70
12	FRONT DOOR OUTER HANDLE RLH <i>New</i>	1	\$ 194.60	\$ 194.60
13	FRONT DOOR POWER WINDOW MOTOR LH <i>New</i>	1	\$ 467.90	\$ 467.90
14	FRONT DOOR REGULATOR LH <i>New</i>	1	\$ 246.70	\$ 246.70
15	FRONT DOOR GLASS CHANNEL LH <i>New</i>	1	\$ 164.90	\$ 164.90
16	FRONT DOOR FRAME WEATHER STRIP LH <i>New</i>	1	\$ 142.70	\$ 142.70
17	CENTER PILLAR LH (OUTER) <i>Repis</i>	1	\$ 926.80	\$ 926.80
18	REAR DOOR LH <i>Dislodged</i>	1	\$ 1,139.50	\$ 1,139.50
19	REAR DOOR OUTER MOULDING LH <i>New</i>	1	\$ 194.30	\$ 194.30
20	REAR DOOR CHECKER LH <i>New</i>	1	\$ 115.20	\$ 115.20
21	REAR DOOR HINGE LH <i>New</i>	2	\$ 58.60	\$ 117.20
22	REAR DOOR INNER LOCK LH <i>Damaged</i>	1	\$ 342.20	\$ 342.20
23	REAR DOOR LOCK CATCHER LH <i>New</i>	1	\$ 41.40	\$ 41.40
24	REAR DOOR WEATHERSTRIP LH <i>New</i>	1	\$ 136.80	\$ 136.80
25	REAR DOOR INNER TRIM LH <i>Cracked</i>	1	\$ 784.40	\$ 784.40
26	REAR DOOR POWER WINDOW MOTOR LH <i>New</i>	1	\$ 463.50	\$ 463.50

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SFU5356J**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 23.04.21
 TIME OF ACCIDENT : 14:30HRS

27	REAR DOOR REGULATOR GEAR LH <i>Damaged</i>	1	\$	231.40	\$	231.40	✓
28	REAR DOOR BLACK STICKER LH <i>New</i>	1	\$	93.60	\$	93.60	✓
29	REAR DOOR FRAME WEATHERSTRIP LH <i>New</i>	1	\$	178.00	\$	178.00	+
30	REAR DOOR SPEAKER LH <i>New</i>	1	\$	214.30	\$	214.30	+
31	REAR DOOR OUTER HANDLE LH <i>New</i>	1	\$	190.60	\$	190.60	+
32	REAR DOOR GLASS CHANNEL LH <i>New</i>	1	\$	97.40	\$	97.40	+
33	REAR DOOR STOPPER LH <i>New</i>	1	\$	18.20	\$	18.20	+
34	REAR BUMPER <i>Replaced</i>	1	\$	490.00	\$	490.00	✓
35	REAR BUMPER SIDE RETAINER <i>New LH</i>	2	\$	39.40	\$	78.80	39.40
36	REAR FENDER LH <i>Dischd</i>	1	\$	898.40	\$	898.40	✓
37	REAR FENDER 1/4 GLASS WITH MOULDING LH <i>New</i>	1	\$	470.90	\$	470.90	60.
38	REAR FENDER INNER PANEL LH <i>Repairs</i>	1	\$	764.30	\$	764.30	+

Door Inner Sound Insulator
x 2 @ 200 400 ✓
New

TOTAL PRICE \$ 13,353.50
 LESS 20% \$ 2,670.70
SUB TOTAL PRICE \$ 10,682.80

6289.1
5031.28

S/N	DESCRIPTION	QTY	UNIT	S/NETT	TOTAL S/NETT	
1	FRONT DOOR WINDOW GLASS SOLAR FILM LH <i>New</i>	1	\$	350.00	\$	350.00 200
2	FRONT DOOR INNER TRIM CLIP (SET) <i>New</i>	1	\$	60.00	\$	60.00
3	CENTER PILLAR (OUTER) SEALANT LH <i>New</i>	1	\$	60.00	\$	60.00
4	CENTER PILLAR INNER TRIM CLIP (SET) <i>New</i>	1	\$	50.00	\$	50.00
5	REAR DOOR TRIM BOARD CLIP (SET) <i>New</i>	1	\$	50.00	\$	50.00 30.
6	REAR FENDER GLASS SOLAR FILM LH <i>New</i>	1	\$	250.00	\$	250.00
7	REAR DOOR GLASS FRAME GARNISH CLIP LH (S) <i>New</i>	1	\$	30.00	\$	30.00
8	REAR DOOR OUTER MOULDING CLIP LH (SET) <i>New</i>	1	\$	30.00	\$	30.00
9	REAR FENDER SEALANT LH <i>New</i>	1	\$	150.00	\$	150.00 60.
10	REAR FENDER COWLING CLIP (SET) <i>New</i>	1	\$	50.00	\$	50.00
11	REAR FENDER INNER TRIM CLIP (SET) <i>New</i>	1	\$	50.00	\$	50.00
12	REAR FENDER QUARTER GLASS SEALANT LH <i>New</i>	1	\$	80.00	\$	80.00 30.
13	REAR FENDER QUARTER GLASS INNER SHIELD LH <i>New</i>	1	\$	60.00	\$	60.00
14	REAR FENDER INNER PANEL SEALANT LH <i>New</i>	1	\$	150.00	\$	150.00
15	REAR BUMPER CLIP (SET) <i>New</i>	1	\$	80.00	\$	80.00 30.
16	REVERSE SENSORS (SET) <i>New</i>	1	\$	220.00	\$	220.00
17	DOOR VISOR (SET) <i>New</i>	1	\$	350.00	\$	350.00 120.
18	SIDE ANGLE MIRROR (SPECIAL TYPE) <i>New</i>	1	\$	40.00	\$	40.00 20.

TOTAL \$ 2,110.00

490

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SFU5356J**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 23.04.21
 TIME OF ACCIDENT : 14:30HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	1000
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	900
3	TUFF COAT	\$ 250.00	80
4	WIRING, BULB CHECKING	\$ 180.00	30
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	80
6	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
7	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	X
8	TRANSFER FRONT DOOR MECHANISM LH	\$ 80.00	✓
9	TRANSFER REAR DOOR MECHANISM LH	\$ 80.00	✓
10	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 80.00	✓
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
12	REMOVE AND REFIX REAR FENDER GLASS LH	\$ 100.00	40
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 5,220.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,792.80
 TOTAL LABOUR COST : \$ 5,220.00
 TOTAL REPAIR COST : \$ 18,012.80

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

Adrian King,
 L/C 04/05/21,

07 Days ✓

Whel: 754128
 L/S: 6.3K ✓

2420