

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB21005159/ABA3Q2
Date: 14/06/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SKK2161S	Insured Vehicle No :	SLT4142A
Date of Loss:	20/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001815

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK2161S	Engine No:	PE21527980
Make & Model:	MAZDA CX-5, 2.0 PREMIUM 2WD I3 (A)	Chassis No:	JM6KF2W7AM0501522
Reg. Date:	30/10/2020 (Man. Year: 2020)	Odometer:	9565 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,816.20	3,962.88	1,853.32	31.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,300.00	1,550.00	54.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,666.20	5,262.88	3,403.32	39.27
Approved Total (Overridden) (S\$)		4,200.00		

(S\$)	8,666.20	4,200.00	4,466.20	51.54
+ GST 7.00/7.00% (S\$)	606.63	294.00	312.63	51.54
Nett Amount (S\$)	9,272.83	4,494.00	4,778.83	51.54
+ Loss of Use (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,101.45		
Global Sum Settlement (S\$)		5,100.00		

INSPECTION

Date of Assignment: 26/04/2021

Date Inspected: 26/04/2021

Estimated Period of Repair: 5.0 days

Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jun 2021)
Parts:	M1-SUV	MAZDA CX-5 2.0 PREMIUM 2WD I3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK2161S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT L/H FENDER	Dented	375.00 F	*375.00 FL
2	1		*FRONT L/H FENDER LOWER GARNISH	Not Necessary	48.00 F	*- FL
3	1		*FRONT L/H FENDER COWLING	Not Necessary	105.00 F	*- FL
4	1		*FRONT L/H FENDER ARCH PROTECTOR	Cut	158.30 F	*158.30 FL
5	8		*FRONT L/H FENDER ARCH PROTECTOR CLIP	Necessary	52.00 F	*20.00 FL
6	1		*FRONT L/H DOOR	Dented	1,359.50 F	*1,359.50 FL
7	2		*FRONT L/H DOOR HINGE	Not Necessary	130.00 F	*- FL
8	1		*FRONT L/H DOOR LOWER GARNISH	Cut	190.00 F	*190.00 FL
9	1		*FRONT L/H RIM	Cut	1,328.20 FS	*800.00 FS
10	1		*FRONT L/H LOWER ARM	Bent	495.00 F	*495.00 FL
11	1		*FRONT L/H KNUCKLE ARM	Damaged	385.00 F	*385.00 FL
12	1		*FRONT L/H KNUCKLE ARM BEARING	Necessary	550.30 F	*550.30 FL
13	1		*FRONT L/H SHOCK ABSORBER	Damaged	420.50 F	*420.50 FL
14	1		*FRONT L/H TIE ROD	Not Necessary	118.00 F	*- FL
15	1		*FRONT L/H TIE ROD END	Not Necessary	101.40 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,816.20	4,753.60
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	790.72
Total Parts (\$)	5,816.20	3,962.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR REMOVE & TRANSFER LH REAR DOOR FITTING	New	300.00	80.00
2	TO CHECK WIRING	New	100.00	30.00
3	TUFF KOTE	New	150.00	40.00
4	TO CHECK WIRING	New	100.00	30.00
5	TO CONDUCT WHEEL ALIGNMENT	New	200.00	80.00
6	TO REMOVE & REFNEW LH FRONT UNDERCARRIAGE	New	250.00	200.00
7	TUFF KOTE	New	150.00	40.00
8	PANEL BEATING	New	800.00	400.00
9	SPRAY PAINTING	New	800.00	400.00
Gross Labour Cost (\$\$)			2,850.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >