



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

India

LKK

Adnan

21/04/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP III (Grab)

Jasper.

Accident date: 20/04/2021

Estimated repair cost for vehicle no: SKK2161S MAZDA CX-5 2.0 AT PREMIUM 20'

CHASSIS: JM6KF2W7AM0501522

S/n	Qty	Items / List	U/price	Amount
1	1	Front L/H Fender <i>Dented</i>		\$375.00 ✓
2	1	Front L/H Fender Lower Garnish <i>new</i>		\$48.00 +
3	1	Front L/H Fender Cowling <i>new</i>		\$105.00 +
4	1	Front L/H Fender Arch Protector <i>cut</i>		\$158.30 ✓
5	8	Front L/H Fender Arch Protector Clip <i>new</i>	\$6.50	\$52.00 20
6	1	Front L/H Door <i>Dented</i>		\$1,359.50 ✓
7	2	Front L/H Door Hinge <i>new</i>	\$65.00	\$130.00 +
8	1	Front L/H Door Lower Garnish <i>cut</i>		\$190.00 ✓
9	1	Front L/H Rim <i>cut</i>		\$1,328.20 800/sw)
10	1	Front L/H Lower Arm <i>Bent</i>		\$495.00 ✓
11	1	Front L/H Knuckle Arm <i>Bent</i>		\$385.00 ✓
12	1	Front L/H Knuckle Arm Bearing <i>New</i>		\$550.30 ✓
13	1	Front L/H Shock Absorber <i>Damaged</i>		\$420.50 ✓
14	1	Front L/H Tie Rod <i>new</i>		\$118.00 +
15	1	Front L/H Tie Rod End <i>new</i>		\$101.40 +

393360 S.N. 800

314688

Subtotal :- \$5,816.20

Labour charges

To check wiring

\$100.00 30

Tuff kote

\$150.00 40

Labour charges

To check wiring

~~\$100.00~~ 30

To conduct wheel alignment

~~\$200.00~~ 80

To remove & refnew Lh front undercarriage

~~\$250.00~~ 200

Tuff kote

~~\$150.00~~ 40

Panel beating

~~\$800.00~~ 400

Spray painting

~~\$800.00~~ 400

Subtotal :- \$2,300.00

Total:- \$8,116.20

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lg
L/S 26/04/21.

Supplementary 05 Aug.
: 80

total: \$246.88

L/S: A.2K

A.2K



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

21/04/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 20/04/2021

Supplementary cost for vehicle no: SKK2161S MAZDA CX-5 2.0 AT PREMIUM 20'

CHASSIS: JM6KF2W7AM0501522

Labour charges

Labour for remove & transfer Lh rear door fitting

\$ ~~300.00~~ 80.

Total : \$ 300.00

Supplementary : 80.