FORTDELGRO ENGINEERING PTE LTD.

AIR ESTIMATE*

EHICLE NO

SHC7085Z

21/04/21

MAKE

HYU-140 MODEL

CHIANG /CHINA

Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	REAR BUMPER COVER			\$1,106.00
-2	REAR BUMPER BRACKET SIDE LH /RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER UNDER COVER			\$228.00
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR PANEL GARNISH			\$57.50
2	REAR BUMPER REFLECTOR LH/RH		\$32.00	\$64.00
				\$1,943.50
	20.00%		1128	\$388.70
	DISCOUNTED TOTAL		902:40	\$1,554.80
1 8	REAR BUMPER MAT			key \$50.00
1 R	EVERSE SENSOR	- 3	, a	\$135.70
			(88.70	\$185.70
La	abour Charge			
Pa	anel Beating		78	\$700.00
Sp	pray Painting Charge		2	7700.00
	neck lighting	3	<u> </u>	\$500.00 × \$50.00
Re	move/refix reverse sensor		660	Ç \$30.00
	ff Kote		()	\$00.00
	TOTAL LABOUR		1110010	\$60.00
1		3 1	164810	\$1,370.00
	ESTIMATE TOTAL		2/5/81200	
		j	. [[]	\$3,110.50
ومالضها			\$60 1648-10 21581200 2days	Land of the second
This	is an initial estimate based on a visual inspection of the a	ahove vo	nicle The Co. I.	بالريادات
be p	repared after the vehicle is surveyed by a motor Surveyo	Sove ve	ncie. The final repair o	uantum will

Tanfin 97495749

WP 2214/212 450pm

L/s Nismy Mor upont

forful ellhourdonom

62 days

LKKA
the Ri

Tores

LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed
- Supplementan it.