

MFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD6611G

DOA: 21.04.2021

Date: 23.04.2021

Make : MERCEDES

Insurance: CHINA TAIPING

Model : E220CDI (E5)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$1,510.00
1	REAR BUMPER REINFORCEMENT			\$1,150.00
1	REAR BUMPER BRACKET RH			\$135.00
1	REAR BUMPER BRACKET LH			\$135.00
	REAR BUMPER LOWER COVER			\$325.00
	<i>Supp</i> <i>Boothed \$2470 bt</i> <i>Boothed blue tec \$90 use</i>			
	SUB TOTAL		5815	\$3,255.00
	LESS 20%			\$651.00
	DISCOUNTED TOTAL		4652	\$2,604.00
1	REAR BUMPER REVERSE SENSOR			\$388.00
			388	\$388.00
	Labour Charge			
	PANEL BEATING			\$450.00
	SPRAY PAINTING CHARGE			\$300.00
	TUFF KOTE			\$50.00
	REMOVE/REFIX REVERSE SENSOR			\$120.00
	<i>Supp</i> <i>Panel beating \$400 200</i> <i>Spray paint \$250.</i>			
	TOTAL LABOUR		1130	\$920.00
	ESTIMATE TOTAL		6170	\$3,912.00
			1584900	
			02 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97490749
 up 23/4/21 12pm
 as rising after repair
 tanpin e lkhant. v v
 03 days

Giti
 225/55R16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: