

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
10 REAR RH SIDE BUMPER UNDER COVER <i>3xnn</i>	1.00	265.98	53.20	212.78	L	Y	<i>?</i>
11 REAR END PANEL <i>repair</i>	1.00	685.30	137.06	548.24	L	Y	<i>R</i>
12 REAR TAILGATE PANEL ASSY <i>Xnn</i>	1.00	2,580.40	516.08	2,064.32	L	Y	<i>X</i>
13 REAR BOOT WEATHERSTRIP <i>Xnn</i>	1.00	269.55	53.91	215.64	L	Y	<i>X</i>
14 REAR BOOT LOCK <i>Xnn</i>	1.00	384.69	76.94	307.75	L	Y	<i>X</i>
15 REAR TAILGATE HYBRID EMBLEM <i>Xnn</i>	1.00	55.20	11.04	44.16	L	Y	<i>X</i>
16 REAR TAILGATE HYUNDAI EMBLEM <i>Xnn</i>	1.00	68.60	13.72	54.88	L	Y	<i>X</i>
17 REAR TAILGATE IONIQ EMBLEM <i>Xnn</i>	1.00	49.50	9.90	39.60	L	Y	<i>X</i>
18 TAILLAMP RH <i>Xnn</i>	1.00	975.64	195.13	780.51	L	Y	<i>X</i>
19 REAR TAILGATE WINDSCREEN MOULDING <i>Xnn</i>	1.00	185.96	37.19	148.77	L	Y	<i>X</i>
UPPER							
20 REAR TAILGATE WINDSCREEN MOULDING <i>Xnn</i>	1.00	175.46	35.09	140.37	L	Y	<i>X</i>
LOWER							
21 RER RH QUARTER PANEL ASSY <i>repair</i>	1.00	2,371.80	474.36	1,897.44	L	Y	<i>R</i>
22 REAR RH FENDER LINER <i>Xnn</i>	1.00	285.10	57.02	228.08	L	Y	<i>X</i>
23 REAR RH QUARTER PANEL AIR VENT <i>del</i>	1.00	189.22	37.84	151.38	L	Y	<i>X</i>
24 REAR RH BLIND SPOT DETECTION UNIT <i>Xnn</i>	1.00	1,635.70	327.14	1,308.56	L	Y	<i>X</i>
ASSY							
25 REAR TAILGATE "6552-1111" STICKER <i>Xnn</i>	1.00	140.00	0.00	140.00	S	Y	<i>X</i>
26 REAR TAILGATE "COMFORT DELGRO" <i>Xnn</i>	1.00	140.00	0.00	140.00	S	Y	<i>X</i>
STICKER							
27 REAR TAILGATE "BOOK NOW" STICKER <i>Xnn</i>	1.00	140.00	0.00	140.00	S	Y	<i>X</i>
28 REAR BUMPER PROTECTOR <i>nn</i>	1.00	170.00	0.00	170.00	S	Y	<i>50</i>
29 REAR BUMPER CLIP SET <i>nn</i>	1.00	85.00	0.00	85.00	S	Y	<i>30</i>
30 REAR REVERSE SENSOR SET <i>Xnn</i>	2.00	1,400.00	0.00	1,400.00	S	Y	<i>X</i>
31 TAILLAMP GUIDE CLIP SET <i>Xnn</i>	1.00	55.00	0.00	55.00	S	Y	<i>X</i>
32 REAR BUMPER UNDER COVER CLIP SET <i>Xnn</i>	1.00	65.00	0.00	65.00	S	Y	<i>X</i>
33 REAR FENDER LINER CLIP SET <i>Xnn</i>	1.00	75.00	0.00	75.00	S	Y	<i>X</i>
34 REAR BUMPER CENTER MOULDING CLIP <i>nn</i>	1.00	65.00	0.00	65.00	S	Y	<i>30</i>
35 REAR BUMPER RETAINER CLIP SET <i>nn</i>	1.00	70.00	0.00	70.00	S	Y	<i>30</i>
36 REAR BUMPER LOWER CENTER MOULDING <i>Xnn</i>	1.00	65.00	0.00	65.00	S	Y	<i>X</i>
CLIP							
37 REAR WINDSCREEN SEALANT <i>Xnn</i>	2.00	180.00	0.00	180.00	S	Y	<i>X</i>
38 REAR WINDSCREEN PRIMER <i>Xnn</i>	2.00	170.00	0.00	170.00	S	Y	<i>X</i>
39 REAR WINDSCREEN GLASS PAD SET <i>Xnn</i>	1.00	65.00	0.00	65.00	S	Y	<i>X</i>
40 REAR END PANEL SEALANT <i>Xnn</i>	2.00	180.00	0.00	180.00	S	Y	<i>X</i>
41 REAR QUARTER PANEL SEALANT <i>Xnn</i>	2.00	180.00	0.00	180.00	S	Y	<i>X</i>
42 REAR SPOILER PAD SET <i>Xnn</i>	1.00	65.00	0.00	65.00	S	Y	<i>X</i>
43 REAR SPOILER CLIP SET <i>Xnn</i>	1.00	65.00	0.00	65.00	S	Y	<i>X</i>
TOTAL:		16,840.14	693.02	14,147.12			
TOTAL PARTS & LABOUR:		21,080.14	2,693.02	18,387.12			

EXCESS/LOADING:\$S 0.00

No. Of Day:

4 days

RE-SURVEY BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$S

DATE OF SURVEY: *27 / 04 / 21 @ 1220*

SURVEYED BY:

RASHU CLKR

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

nature:

Date: