

ASS. REC BY:

AG

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMC3952M

Yr Regn:

29 Jun 2018

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota

Colour

Yellow

Sp. Reading

8296

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / SY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No Body injured.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Inspector's Signature

Inspector's Stamp



Preli. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp. (\$



Rep. Insp. (\$

Survey Fee:

Transportation:

S + RS \$

Fines

Other

TOTAL

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT21/SMC3952M/TPC

AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way
#07-16
Singapore 079120

QUOTATION

Dear Sir,

Cost of Repair to Vehicle SMC3952M

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)
1.	Rear RH passenger door Repair ✓ 1 Due	1	1,410.00	1,410.00
2.	Rear RH passenger door lower protector / scr	1	285.00	285.00
3.	Rear RH passenger door glass outer moulding X, 1 ML	1	166.00	166.00
4.	Rear RH passenger door frame sticker 2 ✓ ML ML	1	73.00	73.00
5.	Rear RH passenger door inner rubber X NN	1	180.00	180.00
6.	Rear RH fender arch garnish / scr	1	207.00	207.00
7.	1 set body fairings SN X NN	1	600.00	600.00
8.	Rear RH passenger door visor SN 2 ✓ ML ML	1	80.00	80.00
9.	Rubber beading SN X NN	1	15.00	15.00
10.	Rear RH passenger emblem SN / ML	1	140.00	140.00
11.	Remove & refit rear RH passenger door mechanism	1	150.00	150.00
12.	Rust proofing	1	100.00	100.00
13.	Labour charges	1	900.00	900.00
14.	Spray painting	1	900.00	900.00


X NN
250
1000

	SUB-TOTAL	S\$5,206.00
--	------------------	--------------------

- Price before 7% gst

Thank you.

Yours faithfully,


Winnie Chai
HP: 9850-9666

3 Days.

part by part.

before paint photos.

Guo Qiang - 82880282

28/4/21

Guo Qiang @ lkkant.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: