

ASS. BY:

REF:

CC6/CTI 21005190/Des³

ASSIGNMENT

COR NOV 2024

From: _____ Date: _____

Estimate Cost: _____

OD / TP RES / OD RES / EVA / INV / MV

To Insp Vehicle No: _____

at Work m/s _____

of _____

Insured _____

Policy # _____

Claims # _____

Sum Insured: _____

Excess: _____

(Check Record)

Make of Vehicle: _____

(Police Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. of Market Value: _____

IDAC Accident Report _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repair: 7 days

Res.: Yes or No

Lima Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD7104YYr Regn: NOV/2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota PriusCC 1798Colour: Blue

A/C: Insured / Std / N/A

Sp. Reading: 734071

T/Radio: Insured / Std / N/A

Eng/No: 2ZRR962747C/No: STDKB3FU103537537

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60 R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMAI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal: S mmR/Bal: S mmL/Bal: S mmL/Bal: S mmD.O.A: 24/04/2021D.O.I: 28/04/2021Survey held at Bojrost in Ming

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Roof top or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Chung Keping GX 3277P17/12/2021Insure 2/5 10,700/- with 7 days of rev

Date/Time, File Pass to?



: Prel. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS: \$ _____

Photos _____

Others _____

Add Fee: ☐

: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Insp (\$ _____)

Report Format: _____

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 26-Apr-21

MODEL: TOYOTA PRIUS

INSURANCE: Chune Te-ping

VEHICLE NO.: SHD 7104Y

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BONNET <i>Bt / Dent</i>	1	\$950.50	\$950.50
BONNET HINGE (LH) <i>Bt</i>	1	\$87.70	\$87.70
RADIATOR GRILLE <i>damaged / moudy</i>	1	\$438.00	\$438.00
RADIATOR GRILLE EMBLEM <i>src</i>	1	\$88.00	\$88.00
FRONT BUMPER COVER <i>turn</i>	1	\$499.90	\$499.90
FRONT SIDE MEMBER SIDE COVER <i>HW</i>	1	\$ 172.50	\$172.50
FRONT BUMPER SPONGE <i>turn</i>	1	\$78.80	\$78.80
FRONT BUMPER LOWER GRILLE <i>HW</i>	1	\$166.90	\$166.90
LAMP ASSY, FOG, LH <i>dislodged / broken</i>	1	\$920.00	\$920.00
FRONT BUMPER SIDE RETAINER <i>W/S broken</i>	1	\$77.00	\$77.00
FRONT UNDER COVER <i>HW</i>	1	\$180.80	\$180.80
FRONT BUMPER TOP GARNISH <i>HW</i>	1	\$225.40	\$225.40
COVER, FRONT BUMPER HOLE, LH <i>regr / src</i>	1	\$28.38	\$28.38
UNIT ASSY, HEADLAMP, LH (LED) <i>broken</i>	1	\$3,455.00	\$3,455.00
HEADLAMP ECU <i>moudy broken</i>	1	\$682.60	\$682.60
HEAD LAMP PANEL (LH) <i>regr</i>	1	\$240.10	\$240.10
TOP PANEL CENTRE <i>Bt / Dent</i>	1	\$364.98	\$364.98
TOP PANEL SIDE <i>Bt / Dent</i>	1	\$145.90	\$145.90
RADIATOR ASSY <i>HW</i>	1	\$1,841.80	\$1,841.80
RADIATOR FAN GRILLE <i>HW</i>	1	\$632.40	\$632.40
GUIDE RADIATOR AIR NO.3 <i>HW</i>	1	\$299.70	\$299.70
DEFLECTOR, RADIATOR SIDE, LH <i>HW</i>	1	\$83.50	\$83.50
STAY, RADIATOR SUPPORT, LH <i>HW</i>	1	\$65.70	\$65.70
RADIATOR FAN BLADE (LH) <i>HW</i>	1	\$233.10	\$233.10
RADIATOR FAN MOTOR (LH) <i>HW</i>	1	\$543.70	\$543.70
RADIATOR FAN COWLING (LH) <i>HW</i>	1	\$451.30	\$451.30
CONDENSER ASSY, W/RECEIVER <i>HW</i>	1	\$1,336.60	\$1,336.60
FENDER SUB-ASSY, FRONT LH <i>Dent</i>	1	\$945.30	\$945.30
FRONT HOUSING ASSY <i>regr</i>	1	\$958.30	\$958.30
FRONT FENDER SHIELD <i>damaged / turn</i>	1	\$38.00	\$38.00
FRONT FENDER SHIELD CLIP <i>HW</i>	1	\$14.90	\$14.90
FRONT FENDER HYBRID EMBLEM, LH <i>HW</i>	1	\$86.50	\$86.50
BRACKET, FRONT SIDE PANEL, LH <i>Bt / Dent</i>	1	\$86.30	\$86.30
FRONT WINDSCREEN SIDE GARNISH <i>dislodged</i>	1	\$186.40	\$186.40
SUB TOTAL			\$16,605.96
LESS 20% <i>25%</i>			\$3,321.19
DISCOUNTED TOTAL			\$13,284.77
COOLANT <i>HW</i>	1	\$45.00	\$45.00
FRONT DOOR COMFORT LOGO <i>HW</i>	1	\$120.00	120

2637-60

8240-38

6180-28

SUB TOTAL			\$165.00
Labour Charge			
Panel Beating	1	\$1,600.00	\$1,600.00
Spray Painting Charge	1	\$1,400.00	\$1,400.00
Wiring Charge	1	\$100.00	\$100.00
Tuff Kote	1	\$100.00	\$100.00
Towing Charge	1	\$80.00	\$80.00
Remove/Refix Radiator	1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00
Remove/Refix Fuse Box	1	\$120.00	\$120.00
Remove/Refix Engine	1	\$600.00	\$600.00
Remove/Refix Dashboard	1	\$350.00	\$350.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
TOTAL LABOUR			\$5,120.00
ESTIMATE TOTAL			\$18,569.77

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

28/04/22 e 1745h

WA Actual

2/5m 7 days.

1 m

2kk Auto

8

7900.28

Supp 5490.32

13390.60

4/5 10,700/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 29-Apr-21

INSURANCE: China Te-ping

MODEL: TOYOTA PRIUS

VEHICLE NO.: SH 7104Y

DESCRIPTION	QTY	LIST PRICE	AMOUNT
FRONT BUMPER REINFORCEMENT <i>st / Dent</i>	1	\$696.40	\$696.40
UNIT ASSY, HEADLAMP, RH (LED) <i>windy broken</i>	1	\$3,455.00	\$3,455.00
FRONT WINDSCREEN GLASS <i>crack</i>	1	\$1,627.30	\$1,627.30
FRONT WINDSCREEN GLASS MOULDING <i>Hec</i>	1	\$208.60	\$208.60
FRONT WINDSCREEN GLASS MOULDING LOWER <i>Hec</i>	1	\$208.60	\$208.60
FRONT WHEEL RIM <i>distorted</i>	1	\$1,570.55	\$1,570.55
FRONT WHEEL RIM CAP <i>distorted / st</i>	1	\$189.60	\$189.60
SUB TOTAL			\$7,956.05
LESS 20% <i>25%</i>			\$1,591.21
DISCOUNTED TOTAL			\$6,364.84
FRONT WINDSCREEN SEALANT <i>Hec</i>	SN 2	\$60.00	\$120.00
FRONT TYRE (LH/RH) <i>cut 50% dep</i>	SN 1	\$216.00	\$216.00
SUB TOTAL			\$336.00
ESTIMATE TOTAL			\$6,700.84

✓
✓ 2637.60
✓
✓
✓ 1555.00
✓
7123.10
5342.32
✓ 40.00
108.00
148.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

30/04/2021 2 0915

HAT Andrew

Tyan

2kk Andv

[Signature]

5490.32