Messages

Claims



General & Workshop D	etails Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
	Summary				
General Details		Wo	orkshop Details		
Involving	TPVD UNKNOWN UNKNOWN (SL	F8635S) Tot	al Rebate 0		
Date of Loss	23 April 2021	Am	ount		
Time of Loss	11:40	Net	tt Loss Amount	\$0.00	
Loss Description	SHC8055D (INSD) FILTER LEFT A SLF8635S (TP)	ND HIT Ass	signed Workshop	LKK AUTO CONSU	LTANTS PTE LTD (TP)
Comment			ys of work mpletion *	20	

Messages

Claims



Details Ve h	icle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	
ails		Summary				
SLF8635S		Pui	rchase Date	DD/MM/YYYY		Ê
SINGAPOR	E	Reş	gistration Date *	14/09/2016		Ê
41894		Age	e of Vehicle	4		
POLICY INFORMATION	ASSESSMENT INFORMATIC	Dr.	iver Details			
	2016		CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION	
			Driver Name	ТВС		
	ails SLF8635S SINGAPOR	ails SLF8635S SINGAPORE 41894 POLICY INFORMATION ASSESSMENT INFORMATIO	Summary ails SLF8635S Pur SINGAPORE Reg 41894 Age POLICY INFORMATION ASSESSMENT INFORMATION Dri 2016	Summary ails SLF8635S Purchase Date SINGAPORE Registration Date * 41894 Age of Vehicle POLICY INFORMATION ASSESSMENT INFORMATION CATEGORY	SUMMARY SINGAPORE Registration Date * 14/09/2016 41894 Age of Vehicle 4 POLICY INFORMATION ASSESSMENT INFORMATION 2016 CATEGORY FNOL INFORMATION	SLF8635S Purchase Date DD/MM/YYYY SINGAPORE Registration Date * 14/09/2016 41894 Age of Vehicle 4 POLICY INFORMATION ASSESSMENT INFORMATION CATEGORY FNOL INFORMATION POST SURVEY INFORMATION POST SURVEY INFORMATION

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Make	TPVD UNKNOWN	AUDI	Date of Birth		DD/MM/YYYY
Model	UNKNOWN	A3 SEDAN 1.4 TFSI (AT	Age	0	
Туре		•	Occupation	Unknown	
Type of Paint			Education Qualification	Other	•
Chassis No		WAUZZZ8V3G1110947	Driving Experience	0	
Engine No		CZC572988	Driver License #		
Engine Capacity		1395	License Type		•
Sum Insured		0	License Issue Date		DD/MM/YYYY

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	
Market Value		0	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		DD/MM/YYYY
Address	SG, Singapore	
Address type	Personal Correspondence	~
Gender	Unknown	~
Marital status	Unknown	•
Identification #	ТВС	

Messages

Claims



General & Workshop De	tails Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	
			Summary			
Detailed Assessment		Со	ndition of Vehicle	e at time of surve	ey .	
Inspection Date *	27/04/2021	Ge	neral condition	Good		•
Total Loss	Yes No	Ste	eering (Serviceable)	Yes	No	
Towing Charges	0		otbrake erviceable)	Yes	No	
Voluntary Excess	0		ndbrake erviceable)	Yes	No	
Compulsory Excess	0	En	gine Modification	Yes	No	
Young/Inexperienced/ Unnamed Driver Excess	0	Pre	e-accident condition	Good		~

0

Tyre Condition

Age of Tyres	
Front Tyre Size	205/55R16
Front left side	MICHELIN6mm
Front right side	MICHELIN6mm
Spare wheel	
Rear Tyre Size	205/55R16
Rear left side	MICHELIN6mm
Rear right side	MICHELIN6mm

Service Requests

Messages

Claims



General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	
Tax Eligibility & Additional	Deduction for Parts						
Depr./Bttr%	0		Salvage%		0		
Discount%	5		Settlement	%	100		
			Paint Labour/	Material Ratio			
Paint Labour Ratio	20		Cash Loss		Yes	No	P y
Paint Material Ratio	80						r t S
							u p p
							i
							e d b
							У

Α

Χ

Α

Save

Messages

Claims



Add		Appro	ve	Deny	Submit	All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	(
	0	1		FRONT BUMPER FASCIA	Damaged	0	1200	No	0	5	0	0	1140	ſ
	0	1		FRONT BUMPER SIDE RETAINER RH	Cracked	0	105	No	0	5	0	0	99.75	F
	0	1		FRONT BUMPER FOGLAMP COVER RH	Missing	0	295	No	0	5	0	0	280.25	ſ
	0	1		FRONT BUMPER SIDE GARNISH RH	Damaged	0	180	No	0	5	0	0	171	F
	0	10		FRONT BUMPER CLIPS	Necessary	0	6	No	0	5	0	0	57	ı

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC (PA
	0	1		HEAD LAMP RH	Cracked	0	1200	No	0	5	0	0	1140	Re
	0	1		FRONT FENDER RH	Dented	0	490	No	0	5	0	0	465.5	Re
	0	1		FRONT FENDER INNER BRACKET	Bent	0	80	No	0	5	0	0	76	Re
	0	1		FRONT FENDER SPLASH SHIELD	Deformed	0	185	No	0	5	0	0	175.75	Re
	0	8		FRONT FENDER SPLASH SHIELD CLIPS	Necessary	0	6	No	0	5	0	0	45.6	Re
	0	3		FRONT FENDER TOP BRACKET	Repair	0	0	No	0	0	0	0	0	D€
	0	1		FRONT KNUCKLE ARM RH	Bent	0	450	No	0	5	0	0	427.5	Re
	0	1		FRONT LOWER ARM	Bent	0	280	No	0	5	0	0	266	Re
	0	1		FRONT ABSORBER	Bent	0	330	No	0	5	0	0	313.5	Re

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEM PARTS	ENTARY	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT
		0	1		FRONT ABSORBER MOUNTING	Serviceable	0	0	No		0	0	0	0
		0	1		FRONT WHEEL BEARING HUP	Bent	0	320	No		0	5	0	0
		0	1		HORN	Cracked	0	145	No		0	5	0	0
Labou	ır													
	Add		Approve		Deny	Submit All								
	EDIT	SR NO	REPAIR/RI (LABOUR)		PART NAME		ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOU	(OMMENT	REMOVE
		0			TOWING		0	0	0	0	Deny			
		0			TO CHECK & ADJUS WHEEL ALIGNMENT AFTER)		0	100	0	0	Reviev	ving		ii
		0			TO TUFF COAT AFFE	ECTED AREAS	0	30	0	0	Reviev	ving		
		0			TO RESET ELECTRIC	CAL MODULE	0	50	0	0	Reviev	ving		
		0			TO REMOVE & REFI) UNDER CARRIAGE	(FRONT RH	0	120	0	0	Reviev	ving		
		0			TO REMOVE & REFIX SPORT RIM & CONT BALANCING		0	0	0	0	Deny			

AC

(PA

D€

Re

Re

ADJUSTED AMOUNT

0

304

137.75

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO RESPRAY AFFECTED AREAS	0	400	0	0	Reviewing		
	0		TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR FRONT RH WHEEL HOUSING PANEL & ALIGNED ALL PARTS	0	500	0	0	Reviewing		

Messages

Claims



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Add		Approve		Deny	Submit	All		
	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	DAYS OF REPAIR : 4 DAYS	Reviewing	0	0		
		0	HEAD LAMP STICKER	Deny	0	0	NOT NECESSARY	
		0	RIM ASSY (SPORT)	Reviewing	0	600	BENT / WARPED	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	TYRE ASSY	Deny	0	0	SERVICEABLE	



Messages

Claims



Assessment Details

General & Workshop	Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary						
Estimated Claim Amount	\$0.00		Adj	usted Claim Amoun	t \$6,899.60	
CATEGORY		ESTIMATE	ADJUSTED			
Spare Parts						
Labour						
Spare Parts						
Miscellaneous						

Submit for Review



Messages


Claims



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary



Messages

Claims



Assessment Details

General & Workshop I	Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary						
Estimated Claim Amount	\$0.00		Adj	usted Claim Amoun	\$5,500.00	
CATEGORY		ESTIMATE	ADJUSTED			
Miscellaneous						

Submit for Review