

REF: ASM/21003203/kp

ASSIGNMENT

源摩哆廠
GUAN MOTOR WORKS

Business Regn. No. 08102600I

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SKZ8405X

NOT AUTHORISE
L1 Sing @ 6950h
Mercury After Paint

5 days

No.	Qty	List Items		
1	1	Rear bumper	1611891880	\$ 1,600.71 ✓
2	1	Rear bumper RH side retainer		\$ 289.70 ✓
3	1	Rear bumper RH "508" emblem		\$ 133.96 ✓
4	1	RH taillamp	98072 42880	\$ 1,307.09 ✓
5	1	Rear RH fender		\$ 2,499.79 X
6	1	Rear RH fender under shield		\$ 288.96 A
7	1 set	Rear fender uner shield clips	5402-88	\$ 40.00 X
8	1	Rear RH sports rims	9650668380	\$ 1,890.71 ✓
9	1	Rear RH lower arm		\$ 700.78 ✓
10	1	Rear RH trailing arm		\$ 500.99 ✓
11	1	Rear RH shock absorber	517855	\$ 600.80 ✓
12	1	Rear RH knuckle arm		\$ 800.87 ✓
13	1	Rear RH wheel hub and bearing	374816	\$ 688.96 ✓
				\$ 11,343.32
			Less 10%	\$ 1,134.33
			Total :	\$ 10,208.99

		Labour	
1	Labour Charges for remove/refit, panel beating and replace accident damages.	\$ 1,100.00	700
2	To putty and spray Spray Paintings charges.	\$ 800.00	600
3	To check wirings and lightings.	\$ 40.00	200
4	To remove, refix roof lining, rear cushion seats & rear upholstery.	\$ 180.00	600
5	To rmove, refix rear RH under carriages.	\$ 250.00	1600
6	To conduct computerise wheel alignment test.	\$ 80.00	600
7	To supply and apply anti rust treatment	\$ 60.00	X
		Total :	\$ 2,510.00

Total Parts and Labour : \$ 12,718.99

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: