

ar fender inner trim boards - L/R @ 781.20

1,563.40

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
GST.M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : HO SOO MUI
23 FERNVALE RD
#20-09
SINGAPORE 797638
TEL: 91505426
ATTN:

Estimate No: MC1901908
Date: 27 Apr 2021
Policy No: P10460086R00
Veh Reg No: SKQ4446B
Make/Model: AUDI A3 SB 1.4 TFSI

Your Ref No: SKQ4446B
Claim Type: Third Party → AG
Accident Date: 24/04/2021
TP Veh Reg No: SMX2883A

LKK
1030

Not whaik
Paying the Pain
1/2 day

Estimate Repair Cost to Vehicle No :SKQ4446B

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 RADIATOR GRILLE	1 PC	475.45	
2 RADIATOR GRILLE EMBLEM	1 PC	93.65	
		569.10	
Less 10%		56.91	512.19
LABOUR			
3 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR FRONT BUMPER INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	200.00	
4 TO SPRAY FRONT BUMPER.	1 PC	300.00	
		500.00	500.00
Total			S\$ 1,012.19
Add GST @ 7%			70.85
Total Amount Payable			S\$ 1,083.04

TOTAL: SINGAPORE DOLLAR ONE THOUSAND EIGHTY THREE AND CENTS FOUR ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Prell. Report

Days Of Repair: