

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

27, Apr 2021

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
AIG Building #07-16
S 079120

Attn; motor claim dept-3rd party claim
Claiming against your insured vehicle no: SFZ7921M
Accident involving vehicle no: SKK1210R/SFZ7921M
DOA: 23/04/2021 AT Yishun Ave 7

Dear officer incharge
Estimate cost of repair for vehicle no: SKK1210R
To supply—

Description	Qty	Amount
Front fender, Lh	1	547.30 ✓
Front fender cowl	1	114.10 X
Cowling clip	1	50.00 X
Front bumper	1	498.90 ?
Bumper retainer, Lh	1	42.00 X
Front door, Lh	1	1,831.10 X
Rear door, Lh	1	1,775.20 X
Rear bumper	1	491.80 X
Front rim	1	320.00 ✓
Parts		5,670.40
Parts less 20%		1,134.08
		4,536.32

Dear officer incharge
Estimate cost of repair for vehicle

To supply—
To remove/reinstall rear windscreen glass
To remove/transfer door glass, power window mechanism to new doors-F n RR
To remove damaged parts and attachments
Cut n weld damaged fender; Repair all dented areas
Replace/align all parts into position
To spray paint

Front door, Lh
Rear door, Lh
Rear bumper
Front fender cowl clip
Parts
Parts less 20%

Dear officer incharge
Estimate cost of repair for vehicle

To supply—
To remove/reinstall rear windscreen

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

180.00 X
150.00 601
1,100.00 701
50.00
498.90
1,500.00 12001

831.10
1,775.20
491.80
7,466.32
320.00
5,670.40
1,134.08
4,536.32

180.00
150.00
1,100.00