

Our Job Ref No : 305465319

Date : 28.04.21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No : SHA3991U CTPL

24/04/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SGN1273R
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$1,490.04
 - (b) Labour Charges \$630.00
 - Total for Part-By-Part Repair Cost** \$2,120.04
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : MS. LOKE YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : NAZ LKK

Date : 29/4/2021

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305465319
REGN NO : SHA3991U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 08.04.2020
DATE/TIME IN : 24.04.2021 11:30
ACCIDENT DATE : 24.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	DEF
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	CRK
0003 04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1	155.00	20.00	124.00	DEF
0004 FNPS	NUMBER PLATE REAR WITH TR	1 N	50.00	2.00-	50.00	NEC
0005 04-01-0104-3919-G	STAY-RR BUMPER RH	1	138.10	20.00	110.48	DEF
0006 04-01-0104-2288-G	BEAM-RR BUMPER	1	394.80	20.00	315.84	DEF
0007 04-01-0104-2370-G	LAMP ASSY-REAR FOG	1	201.50	20.00	161.20	DEF

SUB-TOTAL : 1,490.04

JOB NATURE

0000 PB	PANEL BEATING	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 20-204	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 630.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305465319
REGN NO : SHA3991U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 08.04.2020
DATE/TIME IN : 24.04.2021 11:3
ACCIDENT DATE : 24.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,120.04

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

COMFORT DELGRO ENGINEERING

VEHICLE # SHA3991U
NTUC
305465319

TYPE OF C: TP
SURVEY BY: LKK/ NAZ
DATE : 28/04/2021

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMATE	\$	REMARKS
REAR BUMPER FOG LAMP	1		\$201.50	SEE ATTACHED PHOTO
			\$201.50	

DEF

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA3991U

Make : HYUNDAI

Model : IONIQ(G3)

Date: 26/04/2021

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			DEF \$459.40 /R
10	REAR BUMPER CLIPS			\$22.00 XNN
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25 /CRK
2	REAR BUMPER REINFORCEMENT BRACKET LH RH	Y LHX SUC R14 DEF	\$138.10	\$276.20 ?
1	REAR BUMPER REINFORCEMENT			\$394.80 ? /DEF
1	REAR BUMPER LOWER CTR MOULDING			\$155.00 /DEF
1	REAR BUMPER FOG LAMP			DEF \$201.50 X SUC
1	REAR BUMPER TOWING COVER			\$98.80 X SUC
1	LICENCE LAMP LH RH			\$85.30 ? X SUC
	SUB TOTAL		1,800.05	\$2,144.25
	LESS 20%			\$428.85
	DISCOUNTED TOTAL		1,440.04	\$1,715.40
1	REAR NUMBER PLATE WITH TRIM COVER			\$50.00 /CRK
1	REAR BUMPER REVERSE SENSOR			\$180.00 X SUC
				\$230.00
	Labour Charge			
	PANEL BEATING			\$400.00 350
	SPRAY PAINTING CHARGE			\$300.00 250
	WIRING CHARGE			\$50.00 XNN
	REMOVE/REFIX REVERSE SENSOR			\$80.00 30
	TOTAL LABOUR			\$830.00
	ESTIMATE TOTAL			\$2,775.40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKK

26/4/2021 1400

PIR

2 DAYS

CHECK ITEM PHOTOS

BY PAINT PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: