

**COMFORTDELGRO**  
**ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508989  
Fax: 6546 8156

Our Job Ref No : 305465156  
Date : 27/04/21

**FINALIZATION FORM**

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHD7258L

Date of Accident : 23.04.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FBR2333H

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

**Final Lumpsum Repair cost**

\$1,150.00

\$1,150.00

3. Estimated normal period for repairs: 2 working days:

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : NAZ

Tel : 62148398

Date : 29/4/2021

Fax : 65468156

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	---		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 23.04.2021

Time: 16:13:00

Page: 1

REPAIR ESTIMATE

NTUC - 45  
LKK -



COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO	:	305465156
REGN NO	:	SHD7258L
MILEAGE	:	0000000000
MAKE	:	HYUNDAI
MODEL	:	IONIQ(G2)
DATE OF REGN	:	22.11.2018
DATE/TIME IN	:	23.04.2021 12:00
ACCIDENT DATE	:	23.04.2021

### JOB / PARTS DESCRIPTION

[illegible]

## PART REQUISITION

0001	04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	DEF
0002	04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00	SCR
0003	04-01-0104-0851-G	REAR BUMPER REFLECTOR LH	1	41.45	20.00	33.16	SCR
0004	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	NEL

SUB-TOTAL : 779.28

## JOB NATURE

0000 PB	PANEL BEATING	<del>400.00</del> 350
0001 SP	SPRAYPAINT CHARGE	<del>300.00</del> 250
0002 L	R/I REVERSE SENSOR	120.00 <del>250.00</del> -30

SUB-TOTAL : ~~820.00~~ 630

TOTAL : ~~1,599.28~~ 1,409.28

MVA NAME &amp; SIGNATURE

**SURVEYOR NAME & SIGNATURE**

DATE :

DATE :

NAZLKK 26/4/2021 1200  
LIS  
2 DAYS

## AFTER PAINT PHOTOS

LKK Auto Cons. Hence notify

the Repairer of the following:

- To resurvey here after pray painting

- To display a list of artists having reserve

- Parts:  $\frac{1}{2}$  cup

3. The  $\mathcal{H}_\infty$  norm of the system is  $\gamma = 1.5$ .

Art:

File:

1. The