

Our Job Ref No : 305465454
Date : 29/04/21

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Layang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : NAZ
Vehicle Reg No. : SHC2454A

Fax :


24/04/2021


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SJL1564B
2. The finalized amount shall be:
- | | |
|---|-------------------|
| (a) Spare Parts after List discount | <u>\$1,113.36</u> |
| (b) Labour Charges | <u>\$150.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$1,263.36</u> |
| (c.) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | |
| Final Lumpsum Repair cost | |

3. Estimated normal period for repairs: 1 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance

We confirm the estimates and finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : 
Name : NAZ LKK
Date : 3/5/2021

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305465454
REGN NO : SHC2454A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 10.07.2019
DATE/TIME IN : 24.04.2021 10:35
ACCIDENT DATE : 24.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2538-G MIRROR ASSY-O/S RR VIEW R 1 1,391.70 20.00 1,113.36

SUB-TOTAL : 1,113.36

JOB NATURE

0000 PB PANEL BEATING 50.00

0001 SP SPRAYPAINT CHARGE 100.00

SUB-TOTAL : 150.00

TOTAL : 1,263.36

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

REPAIR ESTIMATE*

VEHICLE NO SHC2454A

MAKE

DATE 24/04/21

MODEL : HYUNDAI IONIQ G2

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT RH WING MIRROR			\$1,391.70
	SUB TOTAL			\$1,391.70
	LESS 20%			\$278.34
	DISCOUNTED TOTAL			\$1,113.36
				#REF!
	Labour Charge			
	Panel Beating			\$150.00
	Spray Painting Charge			\$100.00
	TOTAL LABOUR			\$250.00
	ESTIMATE TOTAL			\$1,363.36

NAZUKK
26/4/2021 1445
PR
BY PAINT PHOTO
1 DAY

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: