

ESTIMATE FOR SFQ133P

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No 49715
Reg No/Reg Date SFQ133P / 19/12/2016
Date In/Mileage / 0
Chassis No WDD2462422J414556
Engine No 27091031043834
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 021 191 Cosmos Blac/ 041 105 Fabric/Leat

Account No	Terms	Date/Time Printed	CSE	Operator
WI000576	Credit	26/04/2021/ 20:53	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M REAR BUMPER C/n	1.00	1544.63	00.00	1544.63
M REAR BUMPER TOP PLATE	1.00	272.36	00.00	272.36
M RH/R BUMPER SIDE BRACKET	1.00	12.82	00.00	12.82
M RH/R FENDER	1.00	2556.79	00.00	2556.79
M RH/R FENDER 3/4 GLASS	1.00	230.78	00.00	230.78
M GLAZING REPAIR KIT	1.00	160.11	00.00	160.11
M RH/R FENDER 3/4 GLASS SEAL	1.00	87.33	00.00	87.33
M ADHESIVE SEALANT	1.00	776.81	00.00	776.81
M RH/R DISC WHEEL	1.00	522.92	00.00	522.92
M RH/R DOOR SHELL	1.00	2008.55	00.00	2008.55
M RH/R DOOR WEATHERSTRIP	1.00	305.97	00.00	305.97
M RH/R DOOR INSULATION	1.00	72.38	00.00	72.38
M RH/R DOOR WINDOW GUIDE RAIL	1.00	133.48	00.00	133.48
M RH/R DOOR LOCK	1.00	324.41	00.00	324.41
M RH/R SHOCK ABSORBER	1.00	293.39	00.00	293.39
M REAR TORSION BAR	1.00	230.04	00.00	230.04
M RH/R TORSION BAR ROD	1.00	60.94	00.00	60.94
M RH/R WHEEL CARRIER	1.00	1308.47	00.00	1308.47
M RH/R WHEEL HUB	1.00	375.32	00.00	375.32
M RH/R TIE ROD	1.00	58.18	00.00	58.18
M RH/R RADIUS ROD	1.00	149.53	00.00	149.53
M RH/R CAMBER ARM	1.00	134.26	00.00	134.26
M RH/R SPRING LINK	1.00	190.69	00.00	190.69

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification is allowed
• Supplemental item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Alan Quek

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272

Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Authorized signatory and company stamp

Nett 24,750.16
7% GST on 24750.16 1732.51

Total Payable 26,482.67

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFQ133P

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No 49715
Reg No/Reg Date SFQ133P / 19/12/2016
Date In/Mileage / 0
Chassis No WDD2462422J414556
Engine No 27091031043834
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 021 191 Cosmos Blac/ 041 105 Fabric/Leat

SFQ133P

Account No	Terms	Date/Time Printed	CSE	Operator
W1000576	Credit	26/04/2021/ 20:53	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M BPNSUN

POLICY NO/ACC DATE : SD20V13959/VPC/ROO / 25-04-2021
DRIVE IN: 26-04-2021 // TP CAR NO: SL08343B (INDIA INTERNATIONAL INS)

DATE IN/DATE SURVEY:

BY/AUTHORIZED ON :

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB

REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR

A BPILAB

INSPECT & CONDUCT WHEEL ALIGNMENT.NETT

S BPNSUB

SUPPLY & TRANSFER 1PC REAR RIGHT RIM

PURCHASE ORDER NO:

A BPILAB

REMOVE & INSTALL REAR SUSPENSION & WHEEL BASE photo?

A BPILAB

TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR.NETT

A BPILAB

REMOVE & REPLACE REAR BUMPER, REAR RIGHT FENDER, REAR RIGHT DOOR &
REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.

A BPIRES

RESpray REAR BUMPER, REAR RIGHT FENDER, REAR RIGHT DOOR
& REAR END PANEL

S BPNTOW

ACCIDENT TOWING FROM 3 JALAN JELITA TO PLSC
USING: KING DOLLEY AND SUNDAY CHARGE
REFER WO: 184473

S BPNSUB

SUPPLY 1PC REAR RIGHT 3./4 GLASS SOLAR FILM
PURCHASE ORDER NO:

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFQ133P

SUPPLEMENTARY

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No **49715**
Reg No/Reg Date **SFQ133P / 19/12/2016**
Date In/Mileage **30/04/2021/ 83162**
Chassis No **WDD2462422J414556**
Engine No **27091031043834**
Make/Model **MB/B 180 SEDAN (W246) "STYLE**
Colour/Trim **021 191 Cosmos Blac/ 041 105 Fabric/Leat**

Account No	Terms	Date/Time Printed	CSE	Operator			
WI000576	Credit	27/05/2021/ 22:51	AQ	305 / Alan Quek Ai Lun			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

M BPNSUN
POLICY NO/ACC DATE :SD20V13959/VPC/ROO // 25-04-2021
DRIVE IN:26-04-2021 // TP CAR NO:SL08343B (INDIA INTERNATIONAL INS)
DATE IN/DATE SURVEY:27-04-2021 // LKK RASUL
BY/AUTHORIZED ON :SUNDARI NAGARAJAN // 30-04-2021
X REAR AXLE CARRIER **bt** /
X HEXALOBULAR BOLT **nec** /
X COMBI-SCREW **nec** /
X COMBINATION BOLT **nec** /
X TWO-COMPONENT ADHESIVE **nec** /
X SEAM SEAL **nec** /
X BLIND RIVET WITH PAN HEAD **nec** /

1.00	1893.93	00.00	1893.93
2.00	16.93	00.00	33.86
2.00	20.98	00.00	41.96
2.00	21.68	00.00	43.36
1.00	102.00	00.00	102.00
1.00	104.99	00.00	104.99
9.00	2.64	00.00	23.76

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Cut & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

	Nett	2,243.86
7% GST on	2243.86	157.07
Total Payable		2,400.93

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383