

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0361/2021/HR
DATE : 27-Apr-21
WIP : 24325

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 27/4/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - John

23-Jun-21

OWNER'S NAME : MR. ANG HAO CHIEH
ADDRESS : 55 CHAI CHEE DRIVE
#08-206
SINGAPORE 460055
TELEPHONE : HP +65 93671672
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210002868
VEHICLE NO : **SMX 4205 U**
MODEL CODE : Q3 1.4 TFSI S TRONIC
MODEL YEAR : 12/1/2021
ENGINE NO : CZD C23822
CHASSIS NO : WAUZZZF3M1064715
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Apr-21
PLACE OF ACCIDENT : NEAR BEDOK NORTH ROAD

ny Boo

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 4205 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,500.00	\$ 1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	5,972.00	\$ 2,272.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 4205 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,153.00	
2	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 59.00	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 217.00	
4	FRONT BUMPER GRILLE - RH	1	\$ 110.00	
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 190.00	
6	FRONT BUMPER ARCH SPOILER	1	\$ 383.00	
7	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 153.00	
8	FRONT BUMPER GUIDE SECTION - RH	1	\$ 39.00	
9	FRONT FENDER - RH	1	\$ 1,286.00	
10	FRONT FENDER ATTACHMENT PARTS	1	\$ 63.00	
11	FRONT FENDER BRACE - RH	1	\$ 88.00	
12	FRONT FENDER BRACKET - RH	1	\$ 32.00	
13	FRONT WHEEL HOUSING LINER - RH	1		
14	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 101.00	
15	HEADLIGHT MOUNTING - RH	1	\$ 118.00	
16	HEADLIGHT - RH	1	\$ 5,589.00	
17	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 536.00	\$ 428.80
18	SUNDRIES		\$ 250.00	
TOTAL SPARE PARTS			\$ 10,367.00	\$ 428.80
TOTAL LABOUR CHARGES			\$ 5,972.00	\$ 2,272.00
GRAND TOTAL			\$ 16,339.00	\$ 2,700.80

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

bl-03/06/21



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT