



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR21005237/Buf3e2 Date: 28/06/2021 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 780B	Veh. Inspected	SKH 4142A
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/04/21/2067	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	28/04/2021
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN GOLF CABRIO 1.4	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WVWZZZ1KZDK003445	Colour	WHITE
Odometer	158365 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	HABILEAD	5 mm
L/H Front Tyre	225/40 R18	HABILEAD	5 mm
R/H Rear Tyre	225/40 R18	HABILEAD	5 mm
L/H Rear Tyre	225/40 R18	HABILEAD	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/04/2021	Inspection Date	07/05/2021
Survey held at	8 Kaki Bukit Ave 4 #01-50, Premier @ Kaki Bukit		
Repairer	FC GARAGE		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	