

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9462A**AAD2104-122**

Not Whistle
Reuney B4 paint
RSP21-95

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

27 APR 2021

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD9462A

JTDKB3FUX03083188

TOYOTA

PRIUS

24/04/2021

AUTO & GENERAL

30/08/2019

PART

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 LENS AND BODY, REAR LAMP, LH
- 1 LENS & BODY, REAR COMBINATION LAMP, LH
- 1 LENS AND BODY, REAR LAMP, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, RH
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH
- 1 WEATHERSTRIP, BACK DOOR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 COVER, FLOOR UNDER, NO.2 (RH)
- 1 COVER, FLOOR UNDER, NO.1 (LH)
- 1 COVER, REAR FLOOR (CTR)

LIST

\$	Buc / B1	442.60	✓
\$	B1	332.70	✓
\$	m1	15.40	✓
\$	B1	576.30	✓
\$	Sm	116.50	X
\$	ng 011	117.70	✓
\$	m3cm	123.70	✓
\$	Sm	502.00	X
\$	Sm	443.30	X
\$	Sm	502.00	X
\$	Sm	451.80	X
\$	B1	650.30	✓
\$	Bu	1,147.80	✓
\$	cm	925.60	✓
\$	Sm	242.50	X
\$	Sm	242.50	X
\$	R	61.00	X
\$	R	61.00	X
\$	Sm	372.30	X
\$	Repears	650.30	X
\$	Sm	241.90	X
\$	Sm	175.10	X
\$	Sm	229.90	X

TOTAL	\$	8,624.20
25%	\$	2,156.05
	\$	6,468.15

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9462A**AAD2104-122****Special Nett**

1SET PARKING AID	\$	700.00	2201n
1SET REAR BUMPER CLIP	\$	95.00	501n
2 WINDSCREEN SEALANT	\$	150.00	801n
1 WINDSCREEN MOULDING	\$	200.00	✓
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	301n
1 REAR TAILGATE TOYOTA LOGO	\$	47.90	✓
1 REAR TAILGATE WORDING 'PRIUS'	\$	54.60	✓
1 REAR TAILGATE WORDING 'HYBRID'	\$	54.60	✓
1 REAR TAILGATE STICKER "Trans-Cab"	\$	80.00	301n
1 REAR TAILGATE STICKER "6555-3333"	\$	80.00	301n
1 REAR BUMPER PROTECTOR	\$	180.00	X
2 SEAM SEALANT	\$	250.00	X
1SET REAR BUMPER RETAINER CLIP	\$	85.00	X
1SET TAILLAMP LOWER CLIP	\$	55.00	X
1SET TAILLAMP UPPER CLIP	\$	55.00	X
1 END PANEL TRIM CLIP	\$	65.00	X
TOTAL	\$	2,282.10	

TOTAL PARTS \$ 8,750.25**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facillitate Bodywork Repair.	\$	300.00	1801
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	6001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2104-122**SHD9462A**

To transfer of Rear Door fittings, attachments and perform water seepage test.	\$	~ 180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	~ 480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	~ 380.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301
Putty And Spray Painting Of The Affected Portion.	\$	2,800.00	8801
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	NA 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	~ 220.00	X
To replace, refix and top up coolant for radiator	\$	~ 170.00	X
To lift-up / out engine with gear box and refit.	\$	~ 440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	~ 380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	~ 380.00	X
TOTAL	\$	10,480.00	