



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 4718E

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | FRONT BUMPER (CONSISTENT) | NOT DAMAGED | 468.20 | - |
| 2 | FRONT BUMPER SIDE RETAINER @\$298.90 (CONSISTENT) | NOT DAMAGED | 597.80 | - |
| 1 | HEADLAMP RH (CONSISTENT) | NOT DAMAGED | 985.40 | - |
| 1 | FRONT DOOR RH (CONSISTENT) | TO REPAIR SEE LABOUR | 1,716.30 | - |
| 1 | FRONT STEP PANEL GARNISH RH (CONSISTENT) | NOT DAMAGED | 187.40 | - |
| 1 | SLIDING DOOR RH (CONSISTENT) | TO REPAIR SEE LABOUR | 1,885.60 | - |
| 1 | SIDE MIRROR RH (CONSISTENT) | NOT DAMAGED | 856.80 | - |
| | LESS 25% DISCOUNT | | -1,674.38 | - |
| | | | 5,023.12 | - |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | SUNDRIES (SN) (CONSISTENT) | NOT NECESSARY | 80.00 | - |
| 1 | FRONT BUMPER CLIPS (SN) (CONSISTENT) | NOT NECESSARY | 50.00 | - |
| 1 | FRONT DOOR SEALANT (SN) (CONSISTENT) | NOT NECESSARY | 100.00 | - |
| 1 | FRONT DOOR DOMPONY STICKER (SN) (CONSISTENT) | NECESSARY | 80.00 | 50.00 |
| 1 | FRONT STEP PANEL GARNISH CLIPS (SN) (CONSISTENT) | NOT NECESSARY | 50.00 | - |
| 1 | SLIDING DOOR SEALANT (SN) (CONSISTENT) | NOT NECESSARY | 100.00 | - |
| 2 | FRONT RIM CAP & REAR RIM CAP @\$295.00 (SN) (CONSISTENT) | NOT NECESSARY | 590.00 | - |
| | | | 1,050.00 | 50.00 |
| <u>LABOUR</u> | | | | |
| | R&R FRONT DOOR COMPONENT. | NOT NECESSARY | 150.00 | - |
| | R&R SLIDING DOOR . | NOT NECESSARY | 250.00 | - |
| | WHEEL ALIGNMENT. | NOT NECESSARY | 200.00 | - |
| | UPHOLSTERY . | NOT NECESSARY | 300.00 | - |
| | PANEL BEATING. | NOT NECESSARY | 1,400.00 | - |
| | RUST PROOFING . | NOT NECESSARY | 200.00 | - |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|----------------------|-----------|---------------------------|-------------------|
| | SPRAY PAINTING. | | 1,400.00 | 600.00 |
| | | | 3,900.00 | 600.00 |
| | GRAND TOTAL | | 9,973.12 | 650.00 |
| RECOMMENDED COST OF REPAIRS | | | | 650.00 |

Report Ref No. CS/ASM21004504/Bpa3q2-1

LIM TEOW GUAN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.