

SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION

INCIDENT NO. : /20210202/0116 LOCATION OF FIRE:

TIME OF CALL: 05:35:32 hrs

Singapore

STATION

COVERAGE: Kallang Fire Station

2. INCIDENT INFORMATION

FIRE INVOLVED: The engine compartment of a BMW car (SMG5366X) at the above said location.

METHOD OF EXTINGUISHMENT: By SCDF crew using two compressed air foam backpacks and a hose reel jet from fire appliances.

PROBABLE CAUSE OF FIRE: Accidental (Overheating/ Electrical origin due to collision)

DAMAGE SUSTAINED:

As a result of the fire, the engine compartment, windscreen and bonnet of the car were damaged. The bonnet and engine compartment of the car (SMG5366X) sustained physical damage from a collision. Also due to the collision, a Hino bus (PC3020S) sustained physical damage to its rear left section.

3. FATALITY/INJURY INFORMATION

NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
Phua Qing Hong, Bryan	S****536Z	Block 657, Yishun Avenue 4, #03-357 Singapore 760657	Others
Joshua Choo Yong Kin	S****984D	Block 663, Yishun Avenue 4, #12-213 Singapore 760663	Others
Nan Sien Nyunt	X****613Z	Not Obtainable	Others

REPORT CERTIFIED TRUE AND CORRECT BY:

EE YONG EN JOEL for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE

This is a computer generated Fire Report. No signature is required.