

Jasper.



[Signature]

27 April 2021

To: Lonpac Insurance Bhd

3rd Party Claim - Motor Claims Department

ESTIMATES FOR - TOYOTA ESTIMA - SLT9281Z

CHASSIS: ACR507058213

Reg = 15 Apr 2008.

COE till = 30 SEP 2027

List Items

S/N	QTY	Description	Unit Price	Amount
1	1	rear bumper <i>Distorted</i>	780.00	\$780.00
2	2	rear bumper tow covers <i>new</i>	50.00	\$100.00
3	2	rear bumper sponges <i>new</i>	135.00	\$270.00
4	2	rear bumper brackets <i>new</i>	90.00	\$180.00
5	1	rear bumper clips (set) <i>new</i>	80.00	\$80.00
6	2	rear bumper side retainers (small) <i>new</i>	85.00	\$170.00
7	2	rear bumper side reflectors <i>new LH side</i>	110.00	\$220.00
8	2	rear bumper side retainers (big) <i>new</i>	125.00	\$250.00
9	1	rear end panel - outer <i>Dented</i>	790.00	\$790.00
10	1	rear end panel - inner <i>Not Required</i>	760.00	\$760.00
11	1	rear end panel trim <i>Dented</i>	190.00	\$190.00
12	1	rear end panel top garnish <i>Dented</i>	210.00	\$210.00
13	1	rear end panel trim clips (set) <i>new</i>	50.00	\$50.00
14	2	rear fenders <i>Reps</i>	1,480.00	\$2,960.00
15	2	rear fenders inner garnish <i>Dented</i>	850.00	\$1,700.00
16	2	rear fenders inner garnish clips (set) <i>new</i>	60.00	\$120.00
17	2	rear fenders inner shields <i>3x4</i>	250.00	\$500.00
18	2	rear fenders inner shields clips (set) <i>new</i>	76.00	\$152.00
19	2	tail lamps <i>new</i>	650.00	\$1,300.00
20	2	tail lamps clips (set) <i>new</i>	60.00	\$120.00
21	1	tailgate <i>Distorted</i>	1,490.00	\$1,490.00
22	2	tailgate hinges <i>new</i>	65.00	\$130.00
23	1	tailgate outer handle <i>new</i>	105.00	\$105.00
24	2	tailgate reverse lamps <i>new</i>	550.00	\$1,100.00
25	1	tailgate centre reflector <i>new</i>	770.00	\$770.00
26	1	tailgate trimboard <i>new</i>	615.00	\$615.00
27	1	tailgate trimboard clips (set) <i>new</i>	80.00	\$80.00
28	1	tailgate weatherstrip <i>cut</i>	360.00	\$360.00
29	2	tailgate top spoiler <i>new</i>	780.00	\$1,560.00
30	1	tailgate top spoiler clips (set) <i>new</i>	50.00	\$50.00
31	2	tailgate side garnishes <i>new</i>	285.00	\$570.00
32	2	tailgate side garnish clips (set) <i>new</i>	30.00	\$60.00
33	1	tailgate top garnish <i>new</i>	350.00	\$350.00
34	1	tailgate wiper blade <i>new</i>	38.00	\$38.00
35	1	tailgate wiper arm <i>new</i>	120.00	\$120.00
36	1	tailgate wiper motor <i>new</i>	380.00	\$380.00
37	1	tailgate lock <i>Damaged</i>	760.00	\$760.00
38	1	tailgate latch <i>new</i>	60.00	\$60.00
39	1	tailgate logo <i>new</i>	70.00	\$70.00
40	1	tailgate emblem - LOGO <i>new</i>	80.00	\$80.00
41	1	tailgate emblem "ESTIMA" <i>new</i>	90.00	\$90.00
42	1	tailgate emblem "AERAS" <i>new</i>	90.00	\$90.00



[Handwritten signature]

43	2	tailgate no plate lamps <i>new</i>	160.00	\$320.00	✓
44	1	rear windscreen moulding <i>new</i>	100.00	\$100.00	✓
45	1	spare tyre compartment panel <i>new</i>	750.00	\$750.00	+
46	1	spare tyre compartment topboard <i>new</i>	425.00	\$425.00	+
47	1	spare tyre compartment top trim <i>new</i>	670.00	\$670.00	+
48				\$0.00	
49				\$0.00	
50				\$0.00	

Total before discount: \$22,095.00

Less 25%: -\$5,523.75

Sub Total: \$16,571.25

8214.
6160.50

SPECIAL NETT ITEMS

S/N	QTY	Description		Price	
1	2	Original TOYOTA Reverse Sensors <i>new</i>	250.00	\$500.00	✓
2	2	rear view camera <i>new</i>		\$380.00	✓
3	1	panel sealant <i>new</i>		\$200.00	60
4	1	rear windscreen glass gum <i>new</i>		\$100.00	60
5	1	number plate and frame <i>new</i>		\$80.00	60

Total: \$1,260.00

1060

LABOUR & MISC. CHARGES

S/N	QTY	Description		Price	
1		panel beating		\$1,900.00	1200
2		spray painting		\$1,900.00	1200
3		rustproofing (mpv)		\$250.00	80
4		remove & refit rear windscreen		\$180.00	120
5		remove & refit reverse sensors and drill holes		\$100.00	50
6		remove & refit rear view camera		\$100.00	50
7		check wiring		\$100.00	30
8		transfer tailgate attachments		\$100.00	80
9		chassis alignment		\$300.00	+
10					

Total: \$4,930.00

2810

Grand Total: \$22,761.25

Lump Sum -20% : \$18,209.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 10030.50
L/S: 8/12

Adrian L
L/S 28/04/21
10 Days