

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
8 Kaki Bukit Ave 4 #08-45/46
Premier@Kaki Bukit S(415875)
Tel : 6702 1555 Fax : 6702 1444

TO : AIG DATE : 27-Apr-21
ATTENTION : MOTOR CLAIMS DEPARTMENT JOB TYPE : T/P CLAIMS
ESTIMATE REPORT :

OWNER PARTICULAR

NAME : SXXXX583E

ADDRESS : *Xiao Tong*

TEL. NO. :

VEHICLE DETAILS

VEHICLE NO. : SMD2845R

MODEL / MAKE : HONDA STREAM

CHASSIS NO. : RN6-1090970

ACCIDENT DETAIL

DATE : 26-Apr-21

TIME : 08:50HRS

OWNER INSURANCE : GREAT EASTERN

POLICY NO. : 2020-V0114677-VDP

QUOTATION SUMMARY

PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR TAILGATE <i>Dented</i>	1	\$ 903.30	\$ 903.30
2	REAR TAILGATE WINDSCREEN MOULDING <i>New</i>	1	\$ 65.40	\$ 65.40
3	REAR TAILGATE OUTER GARNISH <i>Not needed</i>	1	\$ 162.40	\$ 162.40
4	REAR TAILGATE LOGO EMBLEM <i>Not needed</i>	1	\$ 31.90	\$ 31.90
5	REAR TAILGATE STREAM EMBLEM <i>New</i>	1	\$ 31.60	\$ 31.60
6	REAR TAILGATE OUTER LOCK HANDLE <i>New</i>	1	\$ 68.20	\$ 68.20
7	REAR TAILGATE NUMBER PLATE LAMP LH/RH <i>Not needed</i>	2	\$ 32.80	\$ 65.60
8	REAR TAILGATE HINGE LH/RH <i>Not needed</i>	2	\$ 46.20	\$ 92.40
9	REAR TAILGATE DAMPER LH/RH <i>Not needed</i>	2	\$ 126.20	\$ 252.40
10	REAR TAILGATE INNER TRIM BOARD <i>Not needed</i>	1	\$ 141.20	\$ 141.20
11	REAR TAILGATE INNER HANDLE <i>Not needed</i>	1	\$ 25.60	\$ 25.60
12	REAR TAILGATE RUBBER GUIDE STOPPER LH/RH <i>New</i>	2	\$ 9.50	\$ 19.00
13	REAR TAILGATE MECHANISM LOCK <i>Damaged</i>	1	\$ 109.40	\$ 109.40
14	REAR TAILGATE WETHER STRIP <i>Not needed</i>	1	\$ 121.60	\$ 121.60
15	REAR BUMPER <i>Distorted</i>	1	\$ 588.20	\$ 588.20
16	REAR BUMPER TOW HOOK COVER <i>Not needed</i>	1	\$ 23.50	\$ 23.50
17	REAR BUMPER SIDE RETAINER LH/RH <i>New</i>	2	\$ 29.40	\$ 58.80
18	REAR BUMPER LOWER BRACKET LH/RH <i>Not needed</i>	2	\$ 20.60	\$ 41.20
19	REAR TAILLAMP LH/RH <i>Not needed</i>	2	\$ 352.40	\$ 704.80
20	REAR TAILLAMP INNER PANEL LH/RH <i>Not needed</i>	2	\$ 145.90	\$ 291.80
21	REAR TAILLAMP LOWER BRACKET LH/RH <i>Not needed</i>	2	\$ 20.60	\$ 41.20
22	REAR END PANEL <i>Dented</i>	1	\$ 306.70	\$ 306.70
23	REAR END PANEL INNER TOP GARNISH <i>Not needed</i>	1	\$ 116.70	\$ 116.70
24	REAR FENDER INNER TRIM BOARD LH/RH <i>Not needed</i>	2	\$ 197.20	\$ 394.40
25	REAR FENDER INNER AIR VENT LH/RH <i>Not needed</i>	2	\$ 25.70	\$ 51.40
26	REAR FLOOR PANEL <i>Not needed</i>	1	\$ 1,062.70	\$ 1,062.70
27	REAR FLOOR PANEL INNER TOP GARNISH <i>Not needed</i>	1	\$ 130.20	\$ 130.20

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	REAR FLOOR PANEL INNER TOP UPHOLSTERY BOARD LH/RH <i>AP</i>	2	\$ 298.60	\$ 597.20
29	REAR FLOOR SIDE PANEL LH/RH <i>Regis</i>	2	\$ 143.20	\$ 286.40
30	SPARE TYRE BRACKET <i>Me n</i>	1	\$ 121.60	\$ 121.60
31	SPARE TYRE SCREW LOCK SET <i>Me n</i>	1	\$ 39.20	\$ 39.20
32	REAR EXHAUST SILSENER BOX <i>3rd</i>	1	\$ 709.50	\$ 709.50
33	REAR EXHAUST RUBBER MOUNTING <i>Me</i>	2	\$ 24.30	\$ 48.60

TOTAL PRICE \$ 7,704.10
 LESS -20% \$ (1,540.82)
SUB TOTAL PRICE \$ 6,163.28

2670
2136

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER SET <i>Me</i>	1	\$ 100.00	\$ 100.00
2	REAR TAILGATE WINDSCREEN CAMERA RECORDER SET <i>Me</i>	1	\$ 680.00	\$ 680.00
3	REAR TAILGATE OUTER GARNISH CLIPS SET <i>Me n</i>	1	\$ 40.00	\$ 40.00
4	REAR TAILGATE REVERSE CAMERA SET <i>Me n</i>	1	\$ 480.00	\$ 480.00
5	REAR TAILGATE NUMBER PLATE WITH CASING SET <i>Me</i>	1	\$ 65.00	\$ 65.00
6	REAR TAILGATE INNER TRIM BOARD CLIPS SET <i>Me</i>	1	\$ 60.00	\$ 60.00
7	REAR BUMPER CLIPS SET <i>Me</i>	1	\$ 60.00	\$ 60.00
8	REAR BUMPER REVERSE SENSOR SET <i>Damaged</i>	1	\$ 280.00	\$ 280.00
9	REAR TAILLAMP CLIPS SET LH/RH <i>Me</i>	2	\$ 50.00	\$ 100.00
10	REAR END PANEL SEALANT <i>Me</i>	1	\$ 80.00	\$ 80.00
11	REAR END PANEL INNER TOP GARNISH CLIPS SET <i>Me</i>	1	\$ 60.00	\$ 60.00
12	REAR FENDER INNER TRIM BOARD CLIP SET LH/RH <i>Me</i>	2	\$ 60.00	\$ 120.00
13	REAR FLOOR PANEL SEALANT <i>3rd</i>	1	\$ 120.00	\$ 120.00
14	REAR FLOOR PANEL INSULATOR MAT <i>Me</i>	1	\$ 350.00	\$ 350.00
15	REAR FLOOR PANEL INNER TOP GARNISH CLIPS SET <i>Me</i>	1	\$ 60.00	\$ 60.00
16	REAR EXHAUST GASKET <i>Me</i>	1	\$ 25.00	\$ 25.00

TOTAL

\$ 2,680.00

350

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING REAR PORTION

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,800.00	800	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,400.00	800	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 125.00	60	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM	\$ 150.00	120	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	50	
TO DISMANTLE & REPLACED REAR TAILGATE REVERSE CAMERA WITH SETTING	\$ 150.00	50	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	60	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	X	

TOTAL

\$ 4,145.00

1770

QUOTATION SUMMARY

PAGE 04

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	8,843.28
TOTAL LABOUR COST	:	\$	4,145.00
TOTAL REPAIR COST	:	\$	12,988.28

APPROVED DETAILS

NO. OF REPAIR DAYS : DAYS

REPAIR UNDER : PART BY PART OR LUMPSUM

DATE / TIME OF SURVEY :

SURVEYED BY / FROM :

CONTACT NUMBER :

FAX NUMBER :

EMAIL ADDRESS :

DATE / TIME OF RE-SURVEY :

EXCESS :

Adrian Lj

2/s 28/04/21

06 Days.

Total: 4296

2/s: 3.4K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: