



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Ref: CS3/CTI20011654/T1f3e2-1

Date: 30/04/2021

Code: CTI

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SDW 7373J	Veh. Inspected	SMV 2861Z
Policy No.	DMPCSNW00137652000	Coverage (\$)	0.00
Claim No.	SNM20D204043/C02/LEWLC	Excess (\$)	0.00
Assign From	JENNY LEW	Assign Date	24/03/2021

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CAMRY HYBRID	c.c	2487
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTNB23HK903070374	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	MICHELIN	6 mm
L/H Front Tyre	215/55 R17	MICHELIN	6 mm
R/H Rear Tyre	215/55 R17	MICHELIN	6 mm
L/H Rear Tyre	215/55 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	24/10/2020	Inspection Date	01/04/2021
Survey held at	RIGHT CLICK AUTOWORKS PTE LTD 7 SOON LEE STREET, #01-27, ISPACE, SINGAPORE 627608		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
--	------------------------