



# VAC AUTO CENTRE PTE LTD UEN: 200210945Z

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883  
Tel: 8618 8008 | Fax: 6636 5355 | Email: vacauto@singnet.com.sg

## Supplementary Estimate

Regn No : GBF183A

Chassis Number : JTFAT35YX0K206062  
Vehicle Make & Model : Toyota Dyna 150 Manual

ITEM NO	DESCRIPTION OF ITEMS	QUANTITY (Piece/Set)	UNIT PRICE (S\$)	AMOUNT (S\$)
<b>Cost Price:</b>				
1	Front door checker RH <i>twil</i>	1	\$ 88.00	\$ 88.00 ✓
2	Front door rear mudguard RH <i>D.S</i>	1	\$ 175.00	\$ 175.00 ✓
3	Front wheel arch panel RH <i>Baby</i>	1	\$ 225.00	\$ 225.00 ✓
4	Front wheel arch panel top granish RH <i>De</i>	1	\$ 68.00	\$ 68.00 ✓
5	Front wheel khuckle plate RH <i>Bull/cro</i>	1	\$ 82.00	\$ 82.00 ✓
			Sub-total	\$ 638.00
		Add	15%	\$ 95.70
		Cost Price	Total	\$ 733.70

### Labour Charge Items:

1	Labour charge to cut out front pillar, wheel arch panel etc			\$ 1,500.00 <i>800</i>
		Labour Charge	Total	\$ 1,500.00

Overall Estimate Parts & Labour (Supplementary)

Grand total \$ 2,233.70