



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CS/LPC21005258/Utf3e2

Date: 02/06/2021

Code: LPC2

### 1. Policy Particulars :- OWN DAMAGE

<b>Insured Veh.</b>		<b>Veh. Inspected</b>	GBF 183A
<b>Policy No.</b>	Z20VC05005217	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	20/21/21/VC05/024478	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ONG LI LI	<b>Assign Date</b>	28/04/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA DYNA (M)	<b>c.c</b>	2982
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	JTFAT35YX0K206062	<b>Colour</b>	WHITE
<b>Odometer</b>	260285 KM	<b>Steering</b>	AFFECTED
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195 R15	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	195 R15	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	155 R12 (D)	BRIDGESTONE	6/6 mm
<b>L/H Rear Tyre</b>	155 R12 (D)	BRIDGESTONE	6/6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	21/04/2021	<b>Inspection Date</b>	28/04/2021
<b>Survey held at</b>	VAC AUTO CENTRE PL NO.1 KAKI BUKIT AVE 6 #02-11 SINGAPORE 417883		

### 5a. Remarks

A)THE MARKET VALUE IS S\$48,000.00(EST. AVERAGE)  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**