

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
 TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: G3F183A
at Workshop m/s: VAC Auto.
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: \$3100
(Client's Record)
Make of Veh: _____

Veh No: G3F183A Yr Regn: 26/5/16
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CM/
Make: Toyota Dyna c.c 2982
Colour: White A/C: Insured / Std / NI / NA
Sp.Reading: 26028X T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JTFAT35YXOK 206062
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or OK
Brake: In order / Jammed / Leaked / Burnt or OK
Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: \$48.
IDAC Accident Rport: Consistent?: Yes or No
GIA / PR Seen: Consistent?: Yes or No
Est. Repairs: 10 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

N/S	O/S

Tyre Size: F: 195 R15
R: 155 R12
 BS / JUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or
Front R/Bal. 6 mm Rear R/Bal. 6/6 mm
L/Bal. 6 mm L/Bal. 6/6 mm
D.O.A. 21/4/21 D.O.I. 28/4/21
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Frt & R
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	LTA \$17776
	Rep 9500 7100

27/5/21 4/5 \$8300 confirmed with victor
red:15818.65;65%

24,118.65

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 10

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: : Site Insp (\$) ___S + RS ___SI

: Interview (\$) Photos

: Tech. Invs (\$) Others

: Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$ 8300)

TOTAL



VAC AUTO CENTRE PTE LTD

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883
Tel: 8618 8008 Fax: 6636 5355 Email: vacauto@singnet.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

JEN: 200210945Z

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Chassis Number : JTFAT35YX0K206062

Signature:

Vehicle Make & Model : Toyota Dyna 150 Manual

Date:

Regn No : GBF183A

not Adherent
LKR
L/s # 8300
10 days.
Excess 63100

Page 1

ITEM NO	DESCRIPTION OF ITEMS	QUANTITY (Piece/Set)	UNIT PRICE (S\$)	AMOUNT (S\$)
Cost Price:				
1	Front panel top <i>Ben/waged</i>	1	\$ 530.00	\$ 530.00 ✓
2	Front panel emblem "Dyna" <i>11X</i>	1	\$ 45.00	\$ 45.00 X
3	Front panel top seal <i>11X</i>	1	\$ 45.00	\$ 45.00 ✓
4	Front wiper garnish <i>11X</i>	1	\$ 125.00	\$ 125.00 X
5	Front centre grille <i>11X</i>	1	\$ 175.00	\$ 175.00 X
6	Front centre grille clips <i>11X</i>	10	\$ 3.50	\$ 35.00 X
7	Front centre grille emblem <i>11X</i>	1	\$ 45.00	\$ 45.00 X
8	Front corner garnish RH <i>11X</i>	1	\$ 58.00	\$ 58.00 X
9	Front corner garnish RH clips <i>11X</i>	10	\$ 15.00	\$ 150.00 X
10	Front windscreen moulding <i>11X</i>	1	\$ 125.00	\$ 125.00 X
11	Front bumper <i>Dis</i>	1	\$ 220.00	\$ 220.00 ✓
12	Front bumper reinforcement <i>11X</i>	1	\$ 185.00	\$ 185.00 X
13	Front headlamp RH <i>310</i>	1	\$ 240.00	\$ 240.00 ✓
14	Front headlamp bracket RH <i>NS</i>	1	\$ 22.00	\$ 22.00 X
15	Front door RH <i>Dis</i>	1	\$ 680.00	\$ 680.00 ✓
16	Front door outer handle RH <i>Jm</i>	1	\$ 88.00	\$ 88.00 ✓
17	Front door window moulding RH <i>Ben</i>	1	\$ 88.00	\$ 88.00 ✓
18	Front door window regulator RH <i>Dis</i>	1	\$ 115.00	\$ 115.00 ✓
19	Front door window regulator motor RH <i>Jm</i>	1	\$ 280.00	\$ 280.00 ✓
20	Front door hinge RH <i>Twi</i>	2	\$ 56.00	\$ 112.00 ✓
21	Front door weatherstrip <i>Dis</i>	1	\$ 95.00	\$ 95.00 ✓
22	Front door lock <i>Jm</i>	1	\$ 185.00	\$ 185.00 ✓
23	Front door outer trim (black) <i>NS X</i>	1	\$ 430.00	\$ 430.00 X
24	Front door side mirror RH <i>310</i>	1	\$ 95.00	\$ 95.00 ✓
25	Front door side mirror garnish RH <i>11X</i>	1	\$ 45.00	\$ 45.00 X
26	Front door pillar RH <i>2350</i>	1	\$ 238.00	\$ 238.00 ✓
27	Front door inner trim RH <i>Dis</i>	1	\$ 430.00	\$ 430.00 ✓
28	Front dashboard <i>11X</i>	1	\$ 555.00	\$ 555.00 X
29	Front step panel RH <i>310</i>	1	\$ 148.00	\$ 148.00 ✓
30	Front step garnish RH <i>310</i>	1	\$ 118.00	\$ 118.00 ✓
31	Front step panel top garnish RH <i>310</i>	1	\$ 68.00	\$ 68.00 ✓
32	Front step panel mat <i>11X</i>	1	\$ 92.50	\$ 92.50 X
33	Front side shield RH <i>Twi</i>	1	\$ 92.50	\$ 92.50 ✓
34	Front side member panel emblem "D40" <i>11X</i>	1	\$ 45.00	\$ 45.00 X
35	Front side member panel emblem "D40" <i>11X</i>	1	\$ 185.00	\$ 185.00 X
36	Front chassis crossmember <i>Ben/Twi</i>	1	\$ 310.00	\$ 310.00 ✓
37	Rear side tailgate RH <i>R X</i>	1	\$ 680.00	\$ 680.00 X
38	Rear side tailgate floor panel RH <i>211</i>	1	\$ 185.00	\$ 185.00 ✓
39	Front rim RH <i>40 S-N</i>	1	\$ 345.00	\$ 345.00 40 S/N
40	Front lower arm RH <i>310</i>	1	\$ 210.00	\$ 210.00 ✓
41	Front drive steering shaft RH <i>Rock</i>	1	\$ 680.00	\$ 680.00 ✓
42	Front side absorber RH <i>Twi</i>	1	\$ 90.00	\$ 90.00 ✓

Shock

477.5



Regn No : GBF183A

Chassis Number : JTFAT35YX0K206062
 Vehicle Make & Model : Toyota Dyna 150 Manual

ITEM NO	DESCRIPTION OF ITEMS	QUANTITY (Piece/Set)	UNIT PRICE (S\$)	AMOUNT (S\$)
Cost Price:				
43	Front wheel hub RH <i>Best ✓</i>	1	\$ 185.00	\$ 185.00 ✓
44	Front wheel hub bearing RH <i>Daged ✓</i>	1	\$ 185.00	\$ 185.00 ✓
45	Front steering column bracket assembly <i>max</i>	1	\$ 890.00	\$ 890.00 ✓
46	Front steering torque shaft assembly <i>max</i>	1	\$ 920.00	\$ 920.00 X
47	Engine mounting <i>max</i>	1	\$ 88.00	\$ 88.00 X
48	Engine mounting bracket <i>max</i>	1	\$ 85.00	\$ 85.00 X
49	Front chassis frame <i>max</i>	1	\$ 3,150.00	\$ 3,150.00 X
50	Front door glass RH <i>Shotted ✓</i>	1	\$ 225.00	\$ 225.00 ✓
			Sub-total	\$ 14,413.00
		Add	15%	\$ 2,161.95
		Cost Price	Total	\$ 16,574.95
Special Nett Items:				
1	Front panel top company emblem <i>NI</i>	1	\$ 250.00	\$ 250.00 X
2	Front door company emblem <i>NI</i>	1	\$ 120.00	\$ 120.00 X
3	Front tyre <i>ols p 11 17 180 604</i>	1	\$ 200.00	\$ 200.00 100
4	Rear tailgate side company emblem <i>max</i>	1	\$ 280.00	\$ 280.00 X
		S/Nett Items	Total	\$ 850.00

Labour Charge Items:

1	Towing charge <i>FOC X</i>		\$	100.00 X
2	To check electrical wiring systems <i>30</i>		\$	100.00 30
3	To remove and refix front dashboard <i>200</i>		\$	300.00 200
4	To straighten front chassis frame <i>11 X</i>		\$	300.00 X
5	To remove and refix front windscreen <i>60</i>		\$	150.00 60
6	To remove and refix front door glass <i>40</i>		\$	80.00 40
7	To remove and refix roof lining <i>11 X</i>		\$	180.00 X
8	To remove and refix front under carriage assembly <i>✓</i>		\$	180.00 ✓
9	To do wheel alignment <i>60</i>		\$	100.00 60
10	To remove and refix rear side tailgate <i>11 X</i>		\$	100.00 X
11	To remove and refix engine <i>11 X</i>		\$	450.00 X
12	To remove front aircon blower assembly <i>> 100</i>		\$	200.00
13	To remove, refix aircon condenser and refill aircon gas		\$	100.00 100
14	To rust proof affected rear areas <i>NI X</i>		\$	120.00 X
15	To respray painting & etc <i>980</i>		\$	1,000.00 980
16	Panel beating, cut, weld, remove and replacing above parts <i>✓</i>		\$	1,000.00 ✓
	Labour Charge		Total	\$ 4,460.00

Overall Estimate Parts & Labour

Grand total \$ 21,884.95

*Hidden, inaccessible damage parts shall be submitted through supplementary

P-5372.5
P-6010.50
+ 15%
P-6912.07
SN-108
L-3450
1047007
8376
5897.5

**VAC AUTO CENTRE PTE LTD** UEN: 200210945Z

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883

Tel: 8618 8008 | Fax: 6636 5355 | Email: vacauto@singnet.com.sg

Supplementary Estimate

Regn No : GBF183A

Chassis Number : JTFAT35YX0K206062
Vehicle Make & Model : Toyota Dyna 150 Manual

ITEM NO	DESCRIPTION OF ITEMS	QUANTITY (Piece/Set)	UNIT PRICE (S\$)	AMOUNT (S\$)
Cost Price:				
1	Front door checker RH <i>twil</i>	1	\$ 88.00	\$ 88.00 ✓
2	Front door rear mudguard RH <i>Dis</i>	1	\$ 175.00	\$ 175.00 ✓
3	Front wheel arch panel RH <i>Subs</i>	1	\$ 225.00	\$ 225.00 ✓
4	Front wheel arch panel top granish RH <i>De</i>	1	\$ 68.00	\$ 68.00 ✓
5	Front wheel khuckle plate RH <i>Sub/case</i>	1	\$ 82.00	\$ 82.00 ✓
			Sub-total	\$ 638.00
			Add 15%	\$ 95.70
			Cost Price Total	\$ 733.70

Labour Charge Items:

1	Labour charge to cut out front pillar, wheel arch panel etc			\$ 1,500.00 <i>800</i>
		Labour Charge	Total	\$ 1,500.00
Overall Estimate Parts & Labour (Supplementary)			Grand total	\$ 2,233.70