Kaki Bukit Autohub. 2 Kaki Bukit Ave 2, #01-18 Singapore 417921

Tel No.: +65 6842 0051 / 6744 0510 Fax No.: +65 6741 0510

Company Reg. No.: 200616038C GST Registration No.: 200616038C

Our Ref:

**SLA 5948 K** 

Your ref:

**GBB 9962 E** 

27 April 2021

## INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711 Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT: TWINCAR LEASING PTE LTD

**VEHICLE NUMBER: SLA 5948 K** 

YOUR INSURED VEHICLE NUMBER: GBB 9962 E

**ACCIDENT ON 20 Apr 2021 ALONG GREENWICH DRIVE** 

AT ABOUT 07:40 HOURS

We refer to your email/fax dated 27 Apr 2021 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

## N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Avenue 2 #01-18 Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



N-51 AUTOMOTIVE PTE LTD

## FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you! Appointed surveyor:

(Name & Signature):

Date & Time of Inspection: