ASS. REC. BY: REF: MSG/2	1005263/Kg
MP MAPTI	IGNMENT
From:	Puz 12221 4000 10, 15
Estimated Cost: Date:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or Wegon
To Inspect Vehicle No:	Make: Suban Fonsky c.c 1998
at Workshop m/s Chen, 140e	Colour M. D. Cray A/C: Insured / Std / NI / NA
of Am/C	Sp.Reading /2/730 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: JEISTGK85FG 058325
Claims No.	Gen. Cond: 8000'l Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 225/55R18
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MICT OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal, or Market Value:	Front 0 Rear
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. / mm R/Bal. / mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. / mm L/Bal. / mm
Est. Repairs: days Res.: Yes or No	D.O.A. 17/4/21 D.O.I. 24/4/2021
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
· Vehicle: IN / OUT	Mea Ols
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
	\$15.5 E. S.
Confirmed \$8900/10day	s before GST.
(RED:3425.56;27%)	
	123.0
Onte/Time, File Pass to? : Prell. Report Day	ys Of Repair:
	survey No. of Trip: Survey Fee:
1) Outa/Time, File Return to?	Transportation
Add Fee:	: Site Insp (\$) \$ - RSSI
7	: Interview (\$), Fixes
F	Tech Invs (\$) Ohus
Report Format:	Weekend (\$
Lump Sum / I.B.I: (S	TOTAL

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg GST:201001158E RCB NO:201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

Estimate No:

ES2190404/AMK

#24-01 HONG LEONG BUILDING

Date: Policy No: 29 Apr 2021 5107643288-01

SINGAPORE 048581 TEL: 68277660

FAX: 62257402

Veh Reg No:

SGZ2233L

ATTN: Motor Claim Department

Not Norhaise

Make/Model:

SUBARU FORESTER

2.0XT

WS Ref:

TP/MSIG/AMK

Chassis No:

JF1SJGK85FG058325

Claim Type: Accident Date: Third Party 17/04/2021 Chassis No Engine No: Resny Afre Pan Reg. Date:

Engine No:

FA20K964597 22/10/2015

TP Veh Reg No:

GBD2471R

10 days

Estimate Repair Cost to Vehicle No: SGZ2233L

_	Description	U	Price	Quantity	Lis	t Price	Amount
	Description					<u>S\$</u>	<u>S\$</u>
	List Price			7.4	3/170		
1	REAR BUMPER		660.30	1 PC		660.30	
2	REAR BUMPER REINFORCEMENT		320.30	1 PC	Ry	320.30	
3	REAR BUMPER SIDE RETAINER		16.10	2 PC	DIT	32.20	_
4			3.80	5 PC	M	19.00	_
5	REAR BUMPER INNER SHIELD	pillen	64.30	2 PC	1000	128.60	-
6	DEAD DUMBED DU DEEL ECTOP	NISA	24.80	1 PC	mis	24.80	Sec.
7	OISCM	MISGA	437.20	2 PC		874.40	-
8	TOD CARNICH		67.00	1 PC	Mil	67.00	
9	D. C. L. C.		20.30	2 PC	is cm	40.60	4
10		1	,072.80	1 PC		,072.80	
11	DATE DATED DATED		120.80	1 PC	MILLIA		5015m
12	TO THE PROPERTY OF THE PROPERT		560.70	1 PC	no	560.70	_
13		and .	60.40	2 PC		120.80	?
14	TAILGATE WINDSCREEN GLASS	atheres	1,120.80	1 PC		,120.80	
1:	THE WINDSCREEN CLASS MOUII DING		60.40	1 PC	nec	60.40	
10	6 TAILGATE LOGO		65.00	1 PC	ne	65.00	
1	7 TAILGATE EMBLEM 'SUBARU', 'SYMMETRICAL' & 'A'	WD'	72.30	1 PC	ne	72.30	-
1	THE STATE OF THE S		72.30	1 PC	Ne	72.30	_
1	TO A STEEL TO THE TOWN BOARD		190.80	1 PC	Dit	190.80	
2	THE PRIED BUSINE GAPNISH		25.00	1 PC	In	25.00	×
2	TO THE WINDER MOTOR		216.30	1 PC		216.30	7
2	ANDER ARM		43.20	1 PC		43.20	7
2	TO THE WINDER DI ADE		36.30	1 PC		36.30	7
2	TOP CENTRE CARNISH	10.41	160.30	1 PC	cm	160.30	
2	TOUCH SENSOR	nit IRN	360.30	1 PC		360.30	
2	THE SAME AND THE PROPERTY OF THE PARTY OF TH		49.50	1 PC	cm	17.50	
2	THE STATE LAMP		24.30	2 PC	an	48.60	×
2	THE WILLD DRAVE LAMP		170.50	1 PC	By	170.50	
177	9 REAR END PANEL		288.30	1 PC	mycan	288.30	
	O REAR END PANEL INNER TOP GARNISH		40.30	1 PC		5,035 (5)	
	1 REAR SPARE TYRE CENTRE TOOL SPONGE		122.00	1 PC	cm	122.00	
	2 REAR SPARE TYRE RH SIDE SPONGE		32.40	1 PC	Bu		
	2 DEAR RH FENDER		960.80	1 PC		960.80	
	DEAD BUILDER INNER TRIM (LOWER)	P-?	228.40	My IPC		228.40	
-	FEAR RH FENDER MULTER GLASS MOULDING	<i>T</i> = 1	360.80	4		360.80	
	C DEAR RH MUFFLER		608.00	1 PC	,	608.00	_
_	THE RUNGER ER FND CHROME		82.00	1 PC	Ref	82.00	-
3	7 REAR RH MUFFLER END COM				1		

Cheng Hoe Motor Pte Ltd

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

TP/MSIG/AMK

SINGAPORE 048581

TEL: 68277660

68277660

ATTN: Motor Claim Department

Claim Type: Accident Date:

WS Ref:

Third Party 17/04/2021

TP Veh Reg No: GBD2471R

Estimate No:

ES2190404/AMK

Date:

Policy No:

5107643288-01 SGZ2233L

29 Apr 2021

Veh Reg No: SO Make/Model: SU

SUBARU FORESTER

2.0XT

Chassis No:

JF1SJGK85FG058325

Engine No: Reg. Date: FA20K964597

22/10/2015

Estimate Repair Cost to Vehicle No: SGZ2233L

FAX: 62257402

_	Description	U/Price	Quantity	List Price	Amount
38	DEAD DU MHEEL ED DUDDED MOUDITINGS	17.00	2 PC	Z 34.00	
39	in the state of th		1 PC	Bn 125.00	
39	REAR RH FENDER INNER TRIM (UPPER)	125.00	TPC	9,615.90	
			Less 20%	1,923.18	7,692.72
			LC33 L070	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	.,
	Special Net				
40	REAR NUMBER PLATE	35.00	1 PC	35.00	-301n
41	REAR END PANEL SEALANT	40.00	1 PC	Mc 40.00	- 30/2
42	REVERSE SENSOR	200.00	1 SET	ne 200.00	_
43	REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	Me 40.00	
44		30.00	1 PC	na 30.00	16.
45	REAR WINDSCREEN GLASS TINTED FILM	180.00	1 PC	Nec 180.00	15012
				525.00	525.00
	Labour		,	- L	
46	THE RESIDENCE TO OTHER MORNALORY BY ANALER	130.00	1 LA	Bill) 130.00	
47	REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	
48	REMOVE & REFIX REAR RH FENDER QUARTER GLASS	50.00	1 LA	50.00	~
49	REMOVE & REFIX REAR BUMPER &	1,500.00	1 LA	1,500.00	13001
47	ATTACHMENTS, TAILLAMPS, TAILGATE, SPOILER &	,		1,000.00	5001
	ATTACHMENTS:TO CUT, WELD & RENEW REAR END				
	PANEL, REAR RH FENDER; KNOCKING & REPAIR REAR RH				
	CHASSIS FRAME, REAR SPARE TYRE PANEL & REALIGN THE				
50	SAME PUTTY & RESPRAY REAR	1,200.00	1LA	1 200 00	1100
30	BUMPER REINFORCEMENT, REVERSE SENSORS, TAILGATE			1,200.00	
	& SPOILER REAR BOTH FENDERS, REAR RH DOOR, REAR				
	END PANEL, REAR SPARE TYRE PANEL, RH CHASSIS FRAME				
	& ALL AFFECTED AREAS	90.00	11.4		6.1
51	REMOVE & REFIX REAR EXHAUST MUFFLER & REALIGN	80.00	1 LA	80.00	601
	THE SAME REMOVE & REFIX SEAT, CARPET, ROOF LINING TO	150.00	1 LA	150.00	1201
52	FACILITATE REPAIR			100.00	
53	DI ICERDI COEING	120.00	1 LA	120.00	901
55	LNN Auto Consultants hence notifi	y	7	3,350.00	3,350.00
	Une Repairer of the following:		4		
	To resurvey before/after spray painting				
	To display damaged part(s) during resurv	еу		· ·	
	Parts prices are subject to confirmation Third parts suppose a confirmation				
	Third party survey is on a "Without Prejud No illegal modification(s) is allowed	ice" basis	1		
	Supplementary item(s) must be resurveye subject to find every				
	is subject to final approval from Insurance	d <u>and</u> Company			
	Acknowledged by Repairer	-	1		
	Signature:				
	Date:				

CLSH SALES / WORK ORDER

MENG RECOVERY SERVICES

THE HOUSE TOWNING SERVICE

THE TELEVISION AND A TOTAL TOT

no.9078

HOTLINE: 9129 1935

		20	de //co	7
Mess:		18.7		
Velide No. (GZ 11)		NOW NO	SULTU	AL.
FORM CAN THE	CIL	E W	<u>U</u>	
			Chan	
Others.	4 40	53 W		4
CORPS- 10	JATE	I ms	□ cm	☐ ĐM
MOE Velides (me a tome 5 m			三分の外 一	musp
			m F	
		TO MEN	E RECOVERY S	SERVICES

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/04/2021 16:25 (SGT)
Date of Accident	17/04/2021 16:50 (SGT)
Exact Location of Accident	Singapore

Additional Location Information GAMBAS AVE TOWARDS YISHUN BEFORE SEMBAWANG AVE Country/State of Loss

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGZ2233L

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	GOH KAR HOON AGNES
NRIC No	S1589641H
Email Address	AGNESKGOH@GMAIL.COM
Mobile Phone No	(Phone) +65-97531552
Alternative Phone No	+65-97531552

VEHICLE PARTICULARS

Subaru
Forester
Private use
No - Claiming third party
Private car
Auto
2000

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No 5107643288-01
Policy Number	5107043200-01
Cover Note Number	

DRIVER

	GOH KAR HOON AGNES
Name of Driver	S1589641H
NRIC No	

Accident report SN07214J000S

Page 1 of 13

Date Of Birth	10/04/1963
Occupation Date Of P	Indoor
Date Of Driving Pass	07/06/1982
Driving experience	38 YEARS AND 10 MONTHS
Gender	
Gender Mobile M.	Female
Mobile Number	(Phone) +65-97531552
Alt. Phone Number	+65-97531552
Email Address	AGNESKGOH@GMAIL.COM
Address	46 SPRINGSIDE VIEW
Address complement	
Postcode	786263
Is the driver the policyholder?	Yes
If No. Beletiers by the British of t	165
If No, Relationship of the Driver with the Insured	
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
Insurance Company of Other Vehicle Owned by Driver	
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	Collision - Head to Rear
Type of Accident	
Weather Conditions	Raining
Road Surface	Wet
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s)	
soliciting/offering accident claims assistance?	No
DETAILS OF POLICE ACTION	
the second secon	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	
ii yes, agains	
CIRCUMSTANCES OF ACCIDENT	and the second s
REFER TO SKETCH PLAN	
ATTACHMENT(S)	
Are accident photos available for attachment?	Yes
Are accident photos available for attachment? Was there any video captured by Car Camera?	Yes
Was there any video captured by Cai Carriera.	Advise to send to motorvideo@income.com.sg
Reasons for not uploading a video of the accident	Yes
Was there any audio recorded?	165
DETAILS OF OTHE	ER VEHICLE PROPERTY 1
Vehicle Registration Number	GBD2471R
Vehicle Manufacturer	
Vehicle Manutacturer	
Vehicle Model	
Vehicle Variant	
	Commercial vehicle
	Odininoida. Volusio
Vehicle Category Name of Driver	AUO ZHI MIN
Work Permit No	G2071377T
Work Permit 19	(Phone) +65-84215858
Contact Number	
	Page 2 of 13
Accident report SN07214J000S	3-20113
ACCIDENT TOPON	

EANG SALIOUS D
<u> </u>
1100
Telo-