

Survey
29/4/2021
1145 hrs
TGLim lin

NO Resurvey necessary.
All external parts only h

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Company Reg No: 201929175W

Vehicle No: **SLV1162B**
Model and make: **Toyota CH-R**
Chassis No:

Qty	Spare Parts	List Price (\$)	2017
1	Front bumper	\$	✓ 584.25 BR ✓
1	Front bumper lower cover	\$	505.15 NDX
1	Front bumper LH side retainer	\$	87.10 115.18 NEC ✓
1	Front bumper LH parking sensor	\$	195.67 NDX
1	Front bumper LH side grille	\$	89.20 NDX
1	Front bumper reinforcement	\$	296.46 } NDX
1	Front bumper inner sponge	\$	98.15 }
1	Front LH fender	\$	795.00 826.10 DD ✓
1	Front LH fender wheel arch moulding	\$	✓ 155.57 BR ✓
1	Front LH fender splash shield	\$	58.35 NDX
1	LH headlamp assy	\$	2350.95 2,821.40 BR ✓

\$ 3972.87 5,745.48
-25% \$ '993.22 1,436.37
\$ 2,979.65 4,309.11

Qty	Spare Parts	Special Nett (\$)
1set	Front bumper clips	\$ 30.00 70.00 ✓
1set	Front LH fender wheel arch moulding clips	\$ 30.00 50.00 ✓
		60.00

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels	\$ 350.00	800.00 ✓
Spray painting on affected panels	\$ 400.00	700.00 ✓
Check wiring and lighting system	\$	50.00 } NDX
Apply rust coating on affected areas	\$	50.00 }
	750.00	

Lamp beam repair
Repair days 4

Total: \$ 6,029.11
3,789.65
@ 20% 757.93
3,031.72

4/3 3,050/2
TGLim lin
3/5/2021