

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLX7204P
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000
ATTN: Motor Claim Department

Estimate No: ES2190454/YISHUN
Date: 15 May 2021
Policy No: 5099395968-03
Veh Reg No: SLX7204P
Make/Model: TOYOTA TOYOTA VIOS E(AUTO)
Chassis No: MR2B23F3401118304
Engine No: 2NR5210856
Reg. Date: 09/04/2018

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 25/04/2021
TP Veh Reg No: SJR5325S

FAX: 64153727

Not Authorized

1/1 Sup &

Returning After Paint

Friday

Estimate Repair Cost to Vehicle No :SLX7204P

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER	489.10	1 PC	<i>Br</i> 489.10	✓
2 REAR BUMPER SIDE RETAINER	<i>also, 7</i> 133.90	2 PCS	267.80	<i>4+</i>
3 REAR BUMPER CLIP	3.50	6 PCS	<i>na</i> 21.00	✓
4 REAR BOOT	611.90	1 PC	<i>Ry</i> 611.90	✓
5 REAR BOOT LOGO	50.20	1 PC	<i>na</i> 50.20	✓
6 REAR BOOT EMBLEM - VIOS	49.50	1 PC	<i>na</i> 49.50	✓
7 REAR BOOT EMBLEM - E	39.80	1 PC	<i>na</i> 39.80	✓
8 REAR BOOT INNER LOCK	360.42	1 PC	<i>na</i> 360.42	✓
9 REAR BOOT INNER RUBBER	166.40	1 PC	<i>na</i> 166.40	X
10 REAR PANEL	620.00	1 PC	<i>Ry</i> 620.00	<i>2</i>
			2,676.12	
		Less 25%	669.03	2,007.09
Special Net				
11 REVERSE SENSOR	200.00	1 PC	<i>Short</i> 200.00	✓
			200.00	200.00
Labour				
12 TO PANEL BEATING	650.00	1 LA	650.00	<i>600</i>
13 TO PUTTY AND RESPRAY ON REAR BOOT, REAR PANEL, REAR BUMPER	750.00	1 LA	750.00	<i>860</i>
			1,400.00	1,400.00
			Total	S\$ 3,607.09
			Add GST @ 7%	252.50
			Total Amount Payable	S\$ 3,859.59

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE