ASS. REC. BY: Stea - (5/SMR 2)	1205273 [Euf3
From: Date:	Veh No: STZ 457K Yr Regn: 25/10/19 Type M. Car M. Cycle / Bus / Van / Lorry 1. Text / Prime Mover /
TO Inspect Vehicle No: SJZ 457K si Workshop m/s Auto Insure Pte Ltd ci Insured: SMB 224G Policy No. Claims No. BUS/04/21/1050 Sum Insured: Excess: (Client's Record) Make of Veh;	Truck / Trailer or Make: Colour AJC: Insured / Std / Ni / N Sp.Reading 70198 1999 Tradio; Insured / Std / Ni / N Eng/No: C/No: C/No: C/No: Cond: Good / Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Pal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No SIA / PR Seen: Consistent?: Yes or No SIL Repairs: A days Res.: Yes or No Lum Sum: 20 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Tyre Size: F: [95/55/65] R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or TOY/G ON Front Rear R/Bal. G mm UBal. G mr UBal. G mr D.O.A. 26/4/2/ D.O.O.I. 29/4/2/ Survey held Bl Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rev. J.J. The: U/C / Chässis frame / Body Structure affected due to collision
WELLING THE PROPERTY OF THE PR	ays Of Repair: 8 survey No. of Trip: 2 Survey Fee: Transportation: s.RS_SI
экже вып Пр. 1.6. г. \$4700 .	: Interview (\$) Produce : Tech. Inve (%) : Weel end (%)



Auto Insure Pte. Ltd. 6 Marsiling Lane Singapore (739145) E: claims01@autoinsure.com.sg W: www.autoinsure.com.sg T: 3157 2626 F: 6368 0081

GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: SJZ457K (SIEW)

BY EMAIL ONLY

(claims01@autoinsure.com.sg)

Your Ref: SMB224G

ATTENTION: MOTOR CLAIMS DEPT

Email : motor_claims@first-insurance.com.sg

29-Apr-21

First Capital Insurance Limited

6 Raffles Quay #21-00 Singapore 048580

Assessed Vehicle No

Date:

: SJZ457K

Car Make and Model

: PERODUA MYVI EZI 1.3L AT 2WD 5DR

Date of Accident

: 26-Apr-21

Date of Assessment

: 29-Apr-21

We have carried out a physical assessment of SJZ457K at our workshop Auto Insure Pte Ltd sustained damages to the REAR LH portion of the vehicle.

4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the REAR LH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount

L/S

Adjusted Amount

: \$ 8,700.00

Est. Repair Days

Pursuant to your instruction, we have NOT AUTHORIZED repair.

The assessment was conducted on a "WITHOUT PREJUDICE" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the adressee solely in relation to the loss of occurrence in which the assessd vehicle is involved.

No liability or responsibilty whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: SJZ457K Your Ref: SMB224G

s/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
		PARTS REPLACEMENT - LIST ITEMS		
1	1	REAR DOOR LH X		REPAIR
2	1	REAR FENDER LH / 00		\$ 962.40
3	1	REAR FENDER INNER SHIELD LH / TAI		\$ 49.00
4	1	REAR TAIL LAMP LH / DR		\$ 621.50
5	1	REAR TAIL LAMP PANEL LH	Į.	\$ 286.70
6	1	TAILGATE / NO		\$ 702.70
7	1	TAILGATE FINISHER CENTRE X		\$ 264.50
8	1	TAILGATE FINISHER CENTRE LOGO X		\$ 45.20
9	1	TAILGATE EMBLEM MYVI / 1/1		\$ 44.30
10	1	REAR BUMPER / CR		\$ 555.70
	1	REAR BUMPER TOWING COVER LH / Oh		\$ 28.70
11		REAR BUMPER REFLECTOR LH 2 - GR	×	\$ 50.00
12	1	near boiling entire recording to		\$ 47.90
13	1		5.	\$ 104.30
14	1	TAILGATE APERTURE WEATHERSTRIP / TN		\$ 715.30
15	1	REAR END PANEL		\$ 53.40
16	1	REAR END PANEL INNER TRIM		\$ 187.20
17	1	REAR BOOT SIDE TRIM LH	×* ,	REPAIR
18	1	REAR FLOOR PANEL X K	SUB TOTAL	
		 	LESS 10%	T
			TOTAL AMOUNT	7

Our Ref: SJZ457K Your Ref: SMB224G

Your Ref: S/NO	SMB224G QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1 2 3 4 5 6 7 8	1 1 1 1 1 1 1 1 SET	REAR FENDER BODY SEALANT LH REAR TAIL LAMP RIM LH REAR TAIL LAMP PANEL SEALANT LH REAR WINDSCREEN MOULDING REAR WINDSCREEN SEALANT REAR BUMPER CLIPS REAR BUMPER SPOILER / SKIRTING REAR BUMPER REVERSE SENSORS REAR END PANEL SEALANT		\$ nec 60 \ 100.00 \$ nec 60 \ 100.00 \$ 120.00 \$ nec 30 \ 120.00 \$ nec 30 \ 60.00 \$ nec 30 \ 300.00 \$ shid 300.00 \$ shid 200.00 \$ shid 200.00 \$ 80.00
9	1		SUB TOTAL	
			TOTAL PARTS COST	\$ 5,306.92

Our Ref: SJZ457K

Our Ref:	SMB224G				
S/NO	DESCRIPTION		EST. BY WORKSHOP		RKSHOP
<u> </u>	LABOUR & PAINT	WORK			
1	TO REMOVE THE AFFECTED PARTS & FITTING: BEAT & RESHAPE THE AFFECTED AREAS AND AND COMPONE	REPLACED THE DAMAGED PARTS	\$	900	1,000.00
2	TO DELLOWE & DESIT MUDING SUSTEEN		\$	31	120.00
	TO REMOVE & REFIT REAR		\$	120	150.00
3	TO REMOVE & REFIT REAR BUMP		\$	30	120.00
4 5	TO REMOVE & REFIT UPHOSTERY, GARNI		\$	50	150.00
6	TO RESPRAY AND SUPPLY EXPANDABLE ITEN		\$	800	1,100.00
	TO PERFORM ANTI-RUST TREATME		\$	30	60.00
7	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)		\$	30	50.00
8	TO VACUUM, WAXING & CLEAN		\$	X	60.00
9	•		\$	30	50.00
10	TO PERFORM WATER SEEPAGE TEST		\$	0 '	8,166.92
	*	TOTAL BEFORE GST	\$		571.68
		GST 7%	\$		8,738.60
		TOTAL (PARTS & LABOUR):	7		-,

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$ 8,700.00 for lump sum with the third party insurance.

Yours Faithfully,

Jason Heng Claims Director

Steve CLKK) WIL AL 29/4/21, 2007 L/S My AL Sy 8 dys

Les and Consultants hence notify transport of the following:	
·	
1 .	
• 167	
• Summer to the second	Untificity
Acknowledged by Repairer	
Signature:	
Date:	***

221470002 / Auto Insure Pte Ltd [608586] 22147016 : 71/04/2021 13:03 (SGT) 3717016 : 1M Wel LING 5UBM 1: 127/04/2021 13:03 (SGT)) 5UBM 1: 127/04/2021 13:03 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

MPORTANT NOTICE

I. Please report correctly the details of the accident to speed up the claims process.

I. This Form must be completed by the Policyholder and/or the Authorised Driver

Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate information.

policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance or this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for Investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

27/04/2021 13:03 (SGT) Date of Submission 26/04/2021 17:05 (SGT) Date of Accident Exact Location of Accident Yishun Ave 2, Singapore TRAFFIC JUNCTION Additional Location Information Singapore Country/State of Loss

IDETAILS OF OWN VEHICLES

SJZ457K Vehicle Registration Number

INSURED/POLICYHOLDER

Is company? WU JUN KANG Name Of Registered Owner NRIC No SXXXX612C WUJUNKANG38@YAHOO.COM.SG Email Address (Phone) +65-81274598 Mobile Phone No +65-81274598 Alternative Phone No

VEHICLE PARTICULARS

Perodua Model Myvi Exact purpose for which vehicle was being used at time of Private use accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Transmission Auto 1298

INSURANCE COMPANY

China Taiping Insurance (Singapore) Pte. Ltd. Name of Insurance Company Comprehensive Type of Coverage Fleet Policy DMPCSNW00136622000 Policy Number Cover Note Number

DRIVER

WU JUN KANG SXXXX612C

	18/11/1988
A Birth	Indoor
Apation Apation Of Driving Pass Opening Pass	24/08/2011
of Driving Pass	9 YEARS AND 8 MONTHS
and expense	Male
cender	(Phone) +65-81274598
Gender Mobile Number	** *********
Mobile Number All. Phone Number	+65-812/4598 WUJUNKANG38@YAHOO.COM.SG
Email Address	329 TAH CHING RD #19-98
A Advance	329 TAH CHING ROW
Address complement	*
Postcode	610329
to the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
	*
Insurance Company of Other Vehicle Owned by Driver	
GENERAL INFORMATION OF THE ACCIDENT	
GENERAL IN CHIMANET	Deet.
Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet
Road Surface	
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	- /
Was any injured conveyed to hospital by dimensional	Yes
Was any other material or property damaged?	1
Number of Passengers (Including Driver)	· ·
	No
soliciting/offering accident claims assistance?	
DETAILS OF POLICE ACTION	
DETAILS OF POLICE NO.	WATER A STATE OF THE STATE OF T
to the police?	No
Was the accident reported to the police?	No
Was notice of intended Prosecution given:	7
Was notice of intended Prosecution give If yes, against whom?	
CIRCUMSTANCES OF ACCIDENT	
REFER TO SKETCH PLAN	max or post of the second section of the second that the configuration is the second that the second to the second the second to the second the second to th
the second secon	
ATTACHMENT(S)	The second secon
www.auchmont?	No
Are accident photos available for attachment?	Yes
idea confused by Call Calleta: """"	FILE TOO LARGE
- Caractualooding a Vinen in the accident	
Was there any audio recorded?	No
	VEHICLE PROPERTY III
IDETAILS OF OTHER	
18 ⁴ 19 ₇₂	SMB224G
Vehicle Registration Number	SIVIDEETG
Vehicle Manufacturer	•
Vehicle Model	•
Vehicle Variant	•

Bus

Vehicle Variant
Vehicle Colour

Vehicle Category
Name of Driver
Contact Number
Address

ACH PLAN

vishur he a SKETCH PLAN M \$ 52 45 7 ET SM 18 22 4 G.

CN 26 04 2021 at 1705 hrs. [Was at the traffic junction of Vishun Ave 7. While waiting for the lights turn green. I felt an impact from the near and Nearned vehicle is hard coulided extr my vehicle.
on 26/04/2021 at 1705, MS, I wan the traffic Junction of Vishun Ave 1. The traffic Junction of Vishun Ave 1. While naiting for the lights turn green. I felt an impact from the near and realized by head coulided arth my vehicle is head coulided.
the traffic junction of Ishun Aver open. Note that a for the lights then open. I felt an impact from the near and Nearnd related to made coulded extr my related.
the traffic jungitori on the lights turn green Note that an impact from the near and 1. felt an impact from the rear and realized vehicle is had coulided extr my vehicle.
I felt an impact from the near contided neared vehicle is hard coulided extr my vehicle.
nearma remediate onth my vehicle.
nearma remediate onth my vehicle.
nearma remediate onth my vehicle.
enth my runde
Δ

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

GIARMC SketchPlanForm_V3

Date & Time:

Driver's Signature (if driver is not the policyholder)

Date & Time:

Personnel's Signature Reporting

Name: NRIC/FIN No.:

2

sack to OneMotoring

nquire PARF/COE Rebate for Registered Vehicle Vehicle Owner Particulars	Singapore NRIC	Part of the Control o
Owner ID Type:	612C	
Owner ID:	The second secon	
Vehicle Details	SJZ457K	AND AND THE PERSONS
Vehicle No.:	No	Activity & Management of the Co.
Vehicle to be Exported: Intended Deregistration Date:	29 Apr 2021.	Verbines handwalling on
Intended Deregistration	PERODUA	and the second distribution of
Vehicle Make:	MYVI EZI 1.3L AT 2WD 5DR	to the control that the party of the control of
Vehicle Model:	White	to the constitution of the contra
Primary Colour:	2010	on the sale of the state of the sale
Manufacturing Year:	E36C11B	makes to the constitution of the constitution of the
Engine No.:	PM2M301S002408413	particular in Programming Commercial Commerc
Chassis No.:	64.0 kW (85 bhp)	Carlos Company (SPE)
Maximum Power Output:	\$7,793.00	enthalism to respond to the second
Open Market Value:	25 Oct 2010	polynythin despitation to the despitation in
Original Registration Date:	25 Oct 2010	والمعاورة المحاولة والمعاورة والمعاولة والمعاو
First Registration Date:	4	
Transfer Count:	\$7,793.00	
Actual ARF Paid: Intended PARF Rebate Details		
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:		Andrews Andrews Constitute
PARF Rebate Amount:	\$0.00	
Intended COE Rebate Details	2002 E	
COE Expiry Date:	30 Sep 2025	
COE Category:	A - Car (1600cc & below)	er control or control live
COE Period(Years):	5	Water Control of the
PQP Paid:	\$16,570.00	National Assessment State Property
OE Rebate Amount:	\$14,646.00	
otal Rebate Amount:	\$14,646.00	
		the.
ressage OF for this vehicle cannot be further	renewed. The vehicle must be de-registered upon COE expiry or when	uie

The information contained herein is correct as at 29 Apr 2021