

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 04 May 2021

Preliminary Advice

Insured Vehicle No : SMY1907S
TP Vehicle No : SGE13D
Make : MERCEDES-BENZ E250
Date of Inspection : 29/04/2021
Inspection At : COMPLETE VMS PTE LTD (HQ)
176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX
SINGAPORE 575721

Accident Date : 25/04/2021
Assignment Date : 29/04/2021
Est. Duration of Repair : 5

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,465.86
Revised Amount	:S\$	8,750.54
Check Items (Estimated)	:S\$	4,873.73
Total	:S\$	13,624.27

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.