



Not Notified
11 Sep 85250/1
Penny After Pain
4 days

TAN LEONG WAH
BLK 262 TOA PAYOH EAST #27-12
SINGAPORE 310262

Attention : THE OWNER
Contact : 97303113

Estimate : ES007184

Date : 27/04/2021
Vehicle Num. : SGE13D
Make/Model : MERCEDES BENZ E250-23013
Chassis/Eng# : WDD2120362A831470/27492030079C
Accident Date : 25/04/2021
Claim No. :
Reference :
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

1.	1	NETT ITEMS :		
2.	1	BOOT LID		3,108.30 X
3.	1	BOOT LID CHROME GARNISH		323.60 ✓
4.	1	BOOT LID REFLECTOR L/H		499.80 ✓
5.	1	BOOT LID LOCK		339.40 X
6.	1	REAR BUMPER 1821.00		1,856.00 ✓
7.	2	REAR BUMPER BRACKET		165.00 ✓
8.	6	REAR BUMPER CLIP		12.80 ✓
9.	2	REAR BUMPER SIDE RETAINER		58.90 ✓
10.	2	REAR BUMPER SIDE CHROME MOULDING 0166.00		117.80 X
11.	1	REAR BUMPER SPONGE		377.20 X
12.	1	REAR BUMPER REINFORCEMENT		312.00 X
13.	1	REAR BUMPER CENTRE ADAPTOR		870.00 ✓
14.	1	REAR BUMPER LOWER LIP		299.60 ✓
15.	1	REAR BUMPER LOWER LIP CHROME CENTRE GARNISH		298.55 X
16.	2	REAR BUMPER LOWER LIP CHROME SIDE GARNISH L/H		207.90 X
17.	1	TAIL LAMP L/H 717		776.00 ✓
18.	1	REAR END PANEL		787.80 ✓
19.	2	REAR END PANEL TOP GARNISH		1,386.70 X
		FRONT SEAT HEADREST		183.60 ✓
		activated (LR)	971.40	1,942.80 X
		Nett Total S\$:		13,928.85
		10.00% Discount S\$:		1,392.89
				12,535.96

1.	1	SPECIAL NETT ITEMS :		
2.	1	MERCEDES LOGO		72.10 ✓
3.	1	E250 EMBLEM		70.00 ✓
		C & C EMBLEM		79.50 ✓

CONTINUE / ...

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

acknowledged by Repairer

Signature:

Date:



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Page 2 / 2

TAN LEONG WAH
BLK 262 TOA PAYOH EAST #27-12
SINGAPORE 310262

Attention : THE OWNER
Contact : 97303113

Estimate : ES007184

Date : 27/04/2021
Vehicle Num. : SGE13D
Make/Model : MERCEDES BENZ E250-23013
Chassis/Eng# : WDD2120362A831470/274920300790
Accident Date : 25/04/2021
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
4.	1	7G-TRONIC EMBLEM		108.30
5.	2	REVERSE SENSOR	195.00	390.00
6.	2	REVERSE SENSOR HOLDER	25.00	50.00
Special Nett Total S\$:				769.90
LABOUR :				
RUST PROOFING TREATMENT				100.00
CHECK TAIL LAMP AND CHECK WIRING				180.00
SPRAY PAINT DAMAGED AREA AFFECTED				1,100.00
TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR				
CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS				
TO CHANGE FRONT SEAT HEADREST,DIAGNOSE AND RESETTNG				
Labour Total S\$:				3,160.00

SingDollars : Sixteen Thousand Four Hundred Sixty-Five & Cents Eighty-Six Only

Total S\$: 16,465.86
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

TAN LEONG WAH
BLK 262 TOA PAYOH EAST #27-12
SINGAPORE 310262

Attention : THE OWNER

Contact : 97303113

Supplementary Estimate : ES007185

Date : 27/04/2021
Vehicle Num. : SGE13D
Make/Model : MERCEDES BENZ E250-23013
Chassis/Eng# : WDD2120362A831470/274920300790
Accident Date : 25/04/2021
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	NETT ITEMS : REAR BUMPER LOWER BRACKET		
----	---	---	--	--

CA 84.60 ✓


Nett Total S\$:
10.00% Discount S\$:

84.60
8.46

76.14

SingDollars : Seventy-Six & Cents Fourteen Only

Total S\$: 76.14
=====


COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun