



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21005281/Uuf3n2	
			Date: 19/05/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 4929J	Veh. Inspected	SMX 4545M	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/04/21/2076	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	29/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MRHFC5650JT002446	Colour	BLUE	
Odometer	50089 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/45 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S WING MIRROR. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/04/2021	Inspection Date	12/05/2021	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			1 Working Days	