



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21005282/R1vf3e2	
			Date: 17/01/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 4500L	Veh. Inspected	SLS 3649S	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/04/21/2016	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	29/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER PREMIUM 2.0A	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZSU600071225	Colour	MAROON	
Odometer	91531 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	YOKOHAMA	6 mm	
L/H Front Tyre	235/55 R18	YOKOHAMA	6 mm	
R/H Rear Tyre	235/55 R18	YOKOHAMA	6 mm	
L/H Rear Tyre	235/55 R18	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/04/2021	Inspection Date	10/05/2021	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	