



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III20014626/Qqf3e2-1	
			Date: 12/05/2021	
			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 6513Y	Veh. Inspected	SMC 1755D	
Policy No.	MCOM0015	Coverage (\$)	0.00	
Claim No.	MCT20120483	Excess (\$)	0.00	
Assign From	MEKAVATHANAN SARNGAPANI	Assign Date	29/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA C-HR	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	ZYX102112702	Colour	GREY	
Odometer	221142 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/60 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/60 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/60 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/12/2020	Inspection Date	29/12/2020	
Survey held at	160 SIN MING DRIVE# 07-18/19			
Repairer	A T PERFORMANCE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	