Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. F

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Tan Kah Leong Date: 05 May 2021

Preliminary Advice

Insured Vehicle No : SMX2126C

TP Vehicle No : SLJ9576B Accident Date : 24/04/2021
Make : NISSAN QASHQAI Assignment Date : 29/04/2021

Date of Inspection : 03/05/2021 Est. Duration of Repair : 4

Inspection At : WAH HONG MOTORS & CREDIT PTE LTD (HQ)

38 TOH GUAN ROAD EAST, #01-57, ENTERPRISE HUB

SINGAPORE 608581

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,740.40
Revised Amount	:S\$	1,761.50
Check Items (Estimated)	:S\$	773.30
Total	:S\$	2,534.80

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
)	Other comments: