

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0367/2021/HR
DATE : 28-Apr-21
WIP : 255044

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. TAN GEOK CHEONG
ADDRESS : 275A BISHAN STREET 24
#12-120
SINGAPORE 571275
TELEPHONE : HP +65 92988620
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SKK 8337 M**
MODEL CODE : Q3 1.4 TFSI S TRONIC
MODEL YEAR : 25/9/2020
ENGINE NO : CZD 898334
CHASSIS NO : WAUZZZF31L1118993
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Apr-21
PLACE OF ACCIDENT : NEAR KEMBANGAN STN

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKK 8337 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250.
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM & REGAS. (R1234)	S/N \$ 1,700.00	7.
4	TO RENEW THROTTLE BODY AND OTHER ENGINE COMPONENTS.	S/N \$ 480.00	x
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	1000 (Without Lock (arrier) 2250 (With Lock (arrier).
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET AND HINGES.	\$ 3,500.00	1650
SUB TOTAL LABOUR CHARGES		: \$ 12,160.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKK 8337 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	X
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 12,632.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKK 8337 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 2,161.00	✓
2	FRONT BUMPER UPPER CLOSING ELEMENT	2	\$ 118.00	?
3	FRONT BUMPER GRILLE - CENTER <i>Crushed</i>	1	\$ 217.00	✓
4	FRONT BUMPER COVER ?	1	\$ 51.00	?
5	FRONT BUMPER GRILLE - LH / RH <i>RH Delnd</i>	2	\$ 220.00 110.00	
6	FRONT BUMPER LOWER CLOSING ELEMENT ?	1	\$ 190.00	?
7	FRONT BUMPER SPOILER <i>Delnd</i>	1	\$ 383.00	✓
8	FRONT BUMPER BRACKET ?	1	\$ 21.00	?
9	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Delnd</i>	1	\$ 153.00	✓
10	FRONT RADIATOR GRILLE <i>Crushed</i>	1	\$ 1,433.00	✓
11	FRONT RADIATOR STRIKER PLATE ?	1	\$ 244.00	?
12	FRONT RADIATOR COVER CAP ?	1	\$ 45.00	?
13	FRONT RADIATOR BRACKET ?	1	\$ 41.00	?
14	FRONT IN BOARD CAMERA <i>new</i>	1	\$ 1,141.00	+
15	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 102.00	?
16	FRONT BUMPER CARRIER ?	1	\$ 916.00	?
17	FRONT BUMPER GUIDE SECTION - LH / RH ?	2	\$ 78.00	?
18	FRONT BUMPER REINFORCEMENT COVER ?	1	\$ 123.00	?
19	AIR CONDITIONER STICKER <i>new</i>	1	\$ 8.00	✓
20	FRONT LOW TONE HORN - RH ?	1	\$ 130.00	?
SUB TOTAL SPARE PARTS		:	\$ 7,775.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKK 8337 M

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT LOW TONE HORN SPRING HACKLE - RH <i>nen</i>	1	\$ 22.00	+	
22	FRONT PARKING AID SENSOR ?	3	\$ 732.00	?	
23	FRONT PARKING AID SENSOR SEAL RING ?	4	\$ 14.00	?	
24	FRONT BUMPER WIRING SET ?	1	\$ 676.00	?	
25	FRONT FENDER - RH <i>Regis</i>	1	\$ 1,286.00	+	
26	FRONT FENDER ATTACHMENT PARTS	1	\$ 63.00	+	
27	FRONT FENDER BRACE - RH	1	\$ 88.00	+	
28	FRONT FENDER BRACKET - RH	1	\$ 32.00	+	
29	FRONT WHEEL HOUSING LINER	1		+	
30	FRONT FENDER COVER - RH <i>nen</i>	1	\$ 16.00	+	
31	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>nen</i>	1	\$ 101.00	+	
32	FRONT BONNET <i>Dented</i>	1	\$ 3,058.00	✓	
33	FRONT BONNET LID HINGE - LH / RH	2	\$ 146.00	+	
34	FRONT BONNET ATTACHMENT PARTS	1	\$ 296.00	+	
35	FRONT BONNET STRIKER - RH	1	\$ 110.00	+	
36	FRONT BONNET SOUND ABS	1	\$ 219.00	+	
37	FRONT BONNET IMPACT PROTECTION - CENTER <i>nen</i>	1	\$ 28.00	✓	
38	FRONT BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	✓	
39	FRONT BONNET LID LOCK <i>nen</i>	1	\$ 214.00	+	
40	FRONT BONNET RELEASE ELEMENT <i>nen</i>	1	\$ 58.00	+	
SUB TOTAL SPARE PARTS			\$ 7,217.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKK 8337 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT BONNET RELEASE LEVER <i>Free</i>	1	\$ 14.00	+
42	FRONT BONNET RELEASE COVER <i>Free</i>	1	\$ 10.00	+
43	HEADLIGHT MOUNTING - LH / RH ?	2	\$ 236.00	?
44	HEADLIGHT - RH <i>cut</i>	1	\$ 5,589.00	✓
45	HEADLIGHT POWER MODULE <i>Free</i>	1	\$ 758.00	+
46	HEADLIGHT LED <i>Free</i>	1	\$ 781.00	+
47	HEADLIGHT HOSE - RH	1	\$ 24.00	+
48	HEADLIGHT LIFT CYLINDER - RH <i>Free</i>	1	\$ 210.00	+
49	HEADLIGHT LIFT CYLINDER HOSE <i>Free</i>	1	\$ 80.00	+
50	FRONT WHEEL ARCH COVER - LH / RH <i>Free</i>	1	\$ 536.00	✓
51	FRONT RADIATOR LOCK CARRIER ?	1	\$ 1,272.00	?
52	A/C CONDENSER ?	1	\$ 551.00	+
53	A/C CONDENSER SEAL RING <i>Free</i>	1	\$ 10.00	+
54	A/C CONDENSER SEAL RING <i>Free</i>	1	\$ 7.00	+
55	A/C COMPRESSOR REFRIGERANT LINE <i>Free</i>	1	\$ 337.00	+
56	A/C CONDENSER REFRIGERANT LINE <i>Free</i>	1	\$ 330.00	+
57	TEMPERATURE SENSOR HOLDER ?	1	\$ 7.00	?
58	FRONT RADIATOR TEMPERATURE SENSOR ?	1	\$ 59.00	?
59	FRONT RADIATOR INTER COOLER <i>Free</i>	1	\$ 920.00	+
60	FRONT RADIATOR <i>Free</i>	1	\$ 1,035.00	+
SUB TOTAL SPARE PARTS		:	\$ 12,766.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKK 8337 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
61	FRONT RADIATOR FAN <i>the m</i>	1	\$ 1,529.00	<i>+</i>	
62	COOLANT <i>?</i>	6	\$ 269.00	<i>?</i>	
63	FRONT RADIATOR AIR GUIDE - LH / RH <i>?</i>	2	\$ 76.00	<i>?</i>	
64	FRONT RADIATOR UPPER AIR GUIDE <i>?</i>	1	\$ 42.00	<i>?</i>	
65	FRONT RADIATOR LOWER AIR GUIDE <i>?</i>	1	\$ 42.00	<i>?</i>	
66	FRONT RADIATOR INTAKE CONNECTION <i>?</i>	1	\$ 610.00	<i>?</i>	
67	FRONT RADIATOR SEAL <i>men</i>	1	\$ 14.00	<i>+</i>	
68	FRONT RADIATOR INTER COOLER <i>?</i>	1	\$ 775.00	<i>+</i>	
69	FRONT RADIATOR INTER COOLER SEAL <i>the m</i>	1	\$ 17.00	<i>+</i>	
70	FRONT RADIATOR INTER COOLER GASKET <i>?</i>	1	\$ 14.00	<i>+</i>	
71	THROTTLE VALVE ADAPTER <i>Green</i>	1	\$ 824.00	<i>+</i>	
72	THROTTLE VALVE ADAPTER SEAL <i>Green</i>	1	\$ 17.00	<i>+</i>	
73	INTAKE PIPE GASKET <i>?</i>	1	\$ 14.00	<i>+</i>	
74	PRESURE PIPE SEAL RING <i>the m</i>	1	\$ 18.00	<i>+</i>	
75	INTAKE PIPE RETAINING BAR <i>the m</i>	1	\$ 15.00	<i>+</i>	
76	INTAKE PIPE AIR GUIDE <i>?</i>	1	\$ 56.00	<i>+</i>	
77	INTAKE PIPE AIR GUIDE COVER <i>?</i>	1	\$ 29.00	<i>+</i>	
78	AIR FILTER <i>the m</i>	1	\$ 239.00	<i>+</i>	
79	AIR FILTER AIR GUIDE <i>over</i>	1	\$ 20.00	<i>+</i>	
80	WATER DRAINAGE HOSE <i>?</i>	1	\$ 21.00	<i>+</i>	
SUB TOTAL SPARE PARTS		:	\$ 4,641.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKK 8337 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	INTAKE AIR GUIDE ?	1	\$ 34.00	?
82	INTAKE AIR DUCT ?	1	\$ 47.00	?
83	INTAKE MANIFOLD <i>new</i>	1	\$ 121.00	+
84	NOISE INSULATION <i>new</i>	1	\$ 397.00	+
85	FRONT BUMPER PLATE <i>dented</i>	S/N	\$ 60.00	✓
86	SUNDRIES ?		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 33,358.00	
TOTAL LABOUR CHARGES		:	\$ 12,632.00	
GRAND TOTAL		:	\$ 45,990.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ly*
 SURVEYED DATE : *28/04/21*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *And Authorised, 06 Days (Without lock (corner)
 09 Days (With lock (corner)*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT