


PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKK 8337 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250.
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM & REGAS. (R1234)	S/N \$ 1,700.00	✓ 1200.
4	TO RENEW THROTTLE BODY AND OTHER ENGINE COMPONENTS.	S/N \$ 480.00	X
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	1000 (Without Lock Corner) 2250 (With Lock Corner)
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET AND HINGES.	\$ 3,500.00	1650
SUB TOTAL LABOUR CHARGES		\$ 12,160.00	

Car-in

7/5/21

wip= 25504

L2/Hong

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKK 8337 M


Agg- Adam

6/9 days

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER Distorted	1	S	2,161.00	✓
2	FRONT BUMPER UPPER CLOSING ELEMENT R/S Cured	1	S	118.00	✓
3	FRONT BUMPER GRILLE - CENTER Cured	1	S	217.00	✓
4	FRONT BUMPER COVER Delcd	1	S	51.00	✓
5	FRONT BUMPER GRILLE - LH / RH RH Delcd	2	S	220.00	110 ✓
6	FRONT BUMPER LOWER CLOSING ELEMENT Cured Delcd	1	S	190.00	✓
7	FRONT BUMPER SPOILER Delcd	1	S	383.00	✓
8	FRONT BUMPER BRACKET ?	1	S	21.00	?
9	FRONT BUMPER AIR GUIDE GRILLE - RH Delcd	1	S	153.00	✓
10	FRONT RADIATOR GRILLE Cured	1	S	1,433.00	✓
11	FRONT RADIATOR STRIKER PLATE Cured	1	S	244.00	✓
12	FRONT RADIATOR COVER CAP ?	1	S	45.00	?
13	FRONT RADIATOR BRACKET ?	1	S	41.00	?
14	FRONT IN BOARD CAMERA New	1	S	1,141.00	+
15	FRONT BUMPER FOAM FILLER PIECE Cured	1	S	102.00	✓
16	FRONT BUMPER CARRIER Best	1	S	916.00	✓
17	FRONT BUMPER GUIDE SECTION - LH / RH Cured RH	2	S	78.00	39 ✓
18	FRONT BUMPER REINFORCEMENT COVER ?	1	S	123.00	?
19	AIR CONDITIONER STICKER New	1	S	8.00	✓
20	FRONT LOW TONE HORN - RH ?	1	S	130.00	?
SUB TOTAL SPARE PARTS			:	\$ 7,775.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKK 8337 M

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT LOW TONE HORN SPRING HACKLE - RH <i>nen</i>	1	\$ 22.00	+
22	FRONT PARKING AID SENSOR	3	\$ 732.00	?
23	FRONT PARKING AID SENSOR SEAL RING <i>nen</i>	4	\$ 14.00	✓
24	FRONT BUMPER WIRING SET <i>Snapped</i>	1	\$ 676.00	✓
25	FRONT FENDER - RH <i>Reps</i>	1	\$ 1,286.00	+
26	FRONT FENDER ATTACHMENT PARTS	1	\$ 63.00	+
27	FRONT FENDER BRACE - RH	1	\$ 88.00	+
28	FRONT FENDER BRACKET - RH	1	\$ 32.00	+
29	FRONT WHEEL HOUSING LINER	1		+
30	FRONT FENDER COVER - RH <i>nen</i>	1	\$ 16.00	+
31	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>nen</i>	1	\$ 101.00	+
32	FRONT BONNET <i>Dented</i>	1	\$ 3,058.00	✓
33	FRONT BONNET LID HINGE - LH / RH	2	\$ 146.00	+
34	FRONT BONNET ATTACHMENT PARTS	1	\$ 296.00	+
35	FRONT BONNET STRIKER - RH	1	\$ 110.00	+
36	FRONT BONNET SOUND ABS	1	\$ 219.00	+
37	FRONT BONNET IMPACT PROTECTION - CENTER <i>nen</i>	1	\$ 28.00	—
38	FRONT BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	—
39	FRONT BONNET LID LOCK <i>nen</i>	1	\$ 214.00	+
40	FRONT BONNET RELEASE ELEMENT <i>nen</i>	1	\$ 58.00	+
SUB TOTAL SPARE PARTS		:	\$ 7,217.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKK 8337 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT BONNET RELEASE LEVER	1	\$ 14.00	+
42	FRONT BONNET RELEASE COVER	1	\$ 10.00	+
43	HEADLIGHT MOUNTING - LH / RH	2	\$ 236.00	118. RH could
44	HEADLIGHT - RH	1	\$ 5,589.00	cut
45	HEADLIGHT POWER MODULE	1	\$ 758.00	+
46	HEADLIGHT LED	1	\$ 781.00	+
47	HEADLIGHT HOSE - RH	1	\$ 24.00	+
48	HEADLIGHT LIFT CYLINDER - RH	1	\$ 210.00	+
49	HEADLIGHT LIFT CYLINDER HOSE	1	\$ 80.00	+
50	FRONT WHEEL ARCH COVER - LH / RH	1	\$ 536.00	+
51	FRONT RADIATOR LOCK CARRIER	1	\$ 1,272.00	could
52	A/C CONDENSER	1	\$ 551.00	Distorted
53	A/C CONDENSER SEAL RING	1	\$ 10.00	+
54	A/C CONDENSER SEAL RING	1	\$ 7.00	+
55	A/C COMPRESSOR REFRIGERANT LINE	1	\$ 337.00	+
56	A/C CONDENSER REFRIGERANT LINE	1	\$ 330.00	+
57	TEMPERATURE SENSOR HOLDER	1	\$ 7.00	?
58	FRONT RADIATOR TEMPERATURE SENSOR	1	\$ 59.00	?
59	FRONT RADIATOR INTER COOLER	1	\$ 920.00	+
60	FRONT RADIATOR	1	\$ 1,035.00	+
SUB TOTAL SPARE PARTS			\$ 12,766.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKK 8337 M

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
61	FRONT RADIATOR FAN <i>new</i>	1	S	1,529.00	+
62	COOLANT <i>new</i>	6	S	269.00	7
63	FRONT RADIATOR AIR GUIDE - LH <i>new</i>	2	S	26.00 38.	
64	FRONT RADIATOR UPPER AIR GUIDE <i>new</i>	1	S	42.00	✓
65	FRONT RADIATOR LOWER AIR GUIDE <i>new</i>	1	S	42.00	✓
66	FRONT RADIATOR INTAKE CONNECTION	1	S	610.00	?
67	FRONT RADIATOR SEAL <i>new</i>	1	S	14.00	+
68	FRONT RADIATOR INTER COOLER	1	S	775.00	+
69	FRONT RADIATOR INTER COOLER SEAL <i>new</i>	1	S	17.00	+
70	FRONT RADIATOR INTER COOLER GASKET	1	S	14.00	+
71	THROTTLE VALVE ADAPTER <i>new</i>	1	S	824.00	+
72	THROTTLE VALVE ADAPTER SEAL <i>new</i>	1	S	17.00	+
73	INTAKE PIPE GASKET	1	S	14.00	+
74	PRESSURE PIPE SEAL RING	1	S	18.00	+
75	INTAKE PIPE RETAINING BAR	1	S	15.00	+
76	INTAKE PIPE AIR GUIDE	1	S	56.00	+
77	INTAKE PIPE AIR GUIDE COVER	1	S	29.00	+
78	AIR FILTER <i>new</i>	1	S	239.00	+
79	AIR FILTER AIR GUIDE <i>new</i>	1	S	20.00	+
80	WATER DRAINAGE HOSE	1	S	21.00	+
SUB TOTAL SPARE PARTS		:	\$	4,641.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Resurveyed @ 11/05/21
 Adrian King H.F.