

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21005287/ATCE2

Date: 18/08/2021

REFERENCE

Insured/Claimant:	LIM THIAM POH	Policy No:	1800069387-01	
Date of Loss:	26/04/2021	Nature of Claim:	OD	Claim No: 1589018377SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA6554U		
Make & Model:	AUDI A3, 999cc TFSI S TRONIC (LED) (A)	Engine No:	CHZ462599
Reg. Date:	14/06/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V8J1067407
Colour:	Black	Odometer:	60680 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$96,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,808.00	8,507.28	11,300.72	57.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,002.00	3,942.00	6,060.00	60.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	29,810.00	12,449.28	17,360.72	58.24
+ GST 7.00/7.00% (S\$)	2,086.70	871.45	1,215.25	58.24
Nett Amount (S\$)	31,896.70	13,320.73	18,575.97	58.24

INSPECTION

Date of Assignment:	29/04/2021		
Date Inspected:	28/04/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	78.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	160.00 FS	*- FS
5	1		*FRONT BUMPER LOWER CLOSING ELEMENT - CENTER	Not Necessary	536.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LH / RH	N/S Deformed	594.00 FS	*237.20 FS
7	1		*FRONT BUMPER TRIM - LH / RH	Not Necessary	326.00 FS	*- FS
8	1		*FRONT WHEEL HOUSING LINER ADAPTER - LH	Not Necessary	38.00 FS	*- FS
9	1		*FRONT RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
10	1		*FRONT RADIATOR CLOSING ELEMENT	Cracked	191.00 FS	*152.40 FS
11	1		*AIR CONDITIONER STICKER	Necessary	8.00 FS	*5.68 FS
12	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
13	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	188.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	795.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	189.00 FS	*151.20 FS
16	1		*FRONT BUMPER REINFORCEMENT COVER	Cracked	122.00 FS	*97.20 FS
17	1		*FRONT HIGH TONE HORN - LH	Not Necessary	200.00 FS	*- FS
18	1		*FRONT BONNET	Not Necessary	3,134.00 FS	*- FS
19	1		*FRONT BONNET ATTACHMENT PARTS	Not Necessary	165.00 FS	*- FS
20	2		*FRONT BONNET LID HINGE - LH / RH	Not Necessary	124.00 FS	*- FS
21	1		*FRONT BONNET CATCH HOOK	Not Necessary	90.00 FS	*- FS
22	2		*FRONT BONNET STRIKER - LH / RH	Not Necessary	220.00 FS	*- FS
23	1		*FRONT BONNET EDGE PROTECTION	Not Necessary	28.00 FS	*- FS
24	1		*FRONT BONNET CATCH HOOK	Not Necessary	63.00 FS	*- FS
25	2		*FRONT BONNET LID LOCK	Not Necessary	427.00 FS	*- FS
26	1		*FRONT BONNET BOWDEN CABLE - CENTER	Not Necessary	58.00 FS	*- FS
27	1		*FRONT BONNET BOWDEN CABLE COVER - CENTER	Not Necessary	10.00 FS	*- FS
28	1		*FRONT FENDER - LH	Not Necessary	851.00 FS	*- FS
29	5		*POP RIVET	Not Necessary	17.00 FS	*- FS
30	1		*FRONT FENDER ATTACHMENT PARTS - LH	Not Necessary	72.00 FS	*- FS
31	1		*FRONT FENDER BRACE	Not Necessary	96.00 FS	*- FS
32	1		*FRONT FENDER BRACKET - LH	Not Necessary	39.00 FS	*- FS
33	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	169.00 FS	*- FS
34	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	89.00 FS	*- FS
35	1		*HEADLIGHT - LH	Cracked	5,455.00 FS	*4,364.00 FS
36	1		*HEADLIGHT LIFT CYLINDER - LH	Not Necessary	142.00 FS	*- FS
37	1		*FRONT LOWER RADIATOR AIR GUIDE - LH	Cracked	25.00 FS	*19.44 FS
38	1		*FRONT UPPER RADIATOR AIR GUIDE - CENTER	Not Necessary	12.00 FS	*- FS
39	1		*HEADLIGHT WASH WATER RESERVOIR	Not Necessary	206.00 FS	*- FS
40	1		*HEADLIGHT HOSE	Not Necessary	68.00 FS	*- FS
41	1		*FRONT RADIATOR LOCK CARRIER MOUNT	Cracked	727.00 FS	*581.60 FS
42	6		*RADIATOR COOLANT	Necessary	142.00 FS	*113.28 FS
43	1		*FRONT NUMBER PLATE	Dented	60.00 FS	*60.00 FS
44	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 19,808.00 8,507.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,900.00	1,750.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND HINGES	New	3,000.00	550.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			10,002.00	3,942.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >