

CC3/A16721005237/ATC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s: _____

of: _____

Insured: _____

Policy No: 1806 069337-01

Claims No: 158901837786

Sum Insured: _____ Excess: \$0

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 M/s days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMA65544 Yr Regn: 2018, June.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 C.C. 999

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 60680 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU2ZZ8V8J1067407

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16. R: 205/55 R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front / Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 28/04/21

Survey held at Premium.

Des. of Damages / Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time	Action / Instruction
	OD A16.
	Confirm \$12,449 \$12,449.28, 6days (Red: 17360.72: 58%)
	MV: 96K.
	PV: 45.6K
	Nett: 50.4K.

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

3 + RS, SI

Photos

Others

Report Formas: _____

Lump Sum / L.B. (\$ _____)

PREMIUM AUTOMOBILES



88 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0364/2021/HR
DATE : 27-Apr-21
WIP : 24985

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

H. Adrian

6 days - ok - 16 Jun 21

OWNER'S NAME : MR. LIM THIAM POH
ADDRESS : 120A CANBERRA CRESCENT
#09-343
SINGAPORE 751120
TELEPHONE : HP +65 88384835
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800069387-01
VEHICLE NO : SMA 6554 U
MODEL CODE : A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 14/06/2018
ENGINE NO : CHZ 462599
CHASSIS NO : WAUZZZ8V8J1067407
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Apr-21
PLACE OF ACCIDENT : NEAR GOMBAK RISE

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 6554 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	\$ 250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	\$ 1,200.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	\$ 1,750.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND HINGES.	\$ 3,000.00	\$ 550.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ <u>10,002.00</u>	\$ 3,942.00



SUBIROAD 1 SINGAPORE 808888

TEL 888 2922 FAX 888 1183

EMAIL: RONA.PHUA@PREMIUMAUTO.COM.SG / CLANAS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 6554 U

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,987.00	\$ 1,589.60
2	FRONT BUMPER FIXING PARTS	1	\$ 187.00	
3	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 78.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 160.00	
5	FRONT BUMPER LOWER CLOSING ELEMENT - CENTER	1	\$ 536.00	
6	FRONT BUMPER CLOSING ELEMENT - LH/ RH	2	\$ 594.00	\$ 237.20
7	FRONT BUMPER TRIM - LH / RH	1	\$ 326.00	
8	FRONT WHEEL HOUSING LINER ADAPTER - LH	1	\$ 38.00	
9	FRONT RADIATOR GRILLE	1	\$ 1,406.00	\$ 1,124.80
10	FRONT RADIATOR CLOSING ELEMENT	1	\$ 191.00	\$ 152.40
11	AIR CONDITIONER STICKER	1	\$ 8.00	\$ 5.68
12	"CAUTION" STICKER	1	\$ 14.00	\$ 10.88
13	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 188.00	
14	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 795.00	
15	FRONT BUMPER FOAM FILLER PIECE	1	\$ 189.00	\$ 151.20
16	FRONT BUMPER REINFORCEMENT COVER	1	\$ 122.00	\$ 97.20
17	FRONT HIGH TONE HORN - LH	1	\$ 200.00	
18	FRONT BONNET	1	\$ 3,134.00	
19	FRONT BONNET ATTACHMENT PARTS	1	\$ 165.00	
20	FRONT BONNET LID HINGE - LH / RH	2	\$ 124.00	
SUB TOTAL SPARE PARTS		:	\$ 10,442.00	\$ 3,368.96

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED. REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



22, UBI ROAD 1, SINGAPORE 408689

TEL 6386 8888 FAX 6341 1183

EMAIL NDRA.KHAIR@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 9MA 6564 U

S/N	PARTS DESCRIPTION	QTY	S/NETT	DAMAGED PARTS & PRICES	
				REMARKS	
				\$	3,368.96
21	FRONT BONNET CATCH HOOK	1	\$ 90.00		
22	FRONT BONNET STRIKER - LH / RH	2	\$ 220.00		
23	FRONT BONNET EDGE PROTECTION	1	\$ 28.00		
24	FRONT BONNET CATCH HOOK	1	\$ 63.00		
25	FRONT BONNET LID LOCK	2	\$ 427.00		
26	FRONT BONNET BOWDEN CABLE - CENTER	1	\$ 58.00		
27	FRONT BONNET BOWDEN CABLE COVER - CENTER	1	\$ 10.00		
28	FRONT FENDER - LH	1	\$ 851.00		
29	POP RIVERT	5	\$ 17.00		
30	FRONT FENDER ATTACHMENT PARTS - LH	1	\$ 72.00		
31	FRONT FENDER BRACE	1	\$ 96.00		
32	FRONT FENDER BRACKET - LH	1	\$ 39.00		
33	FRONT WHEEL HOUSING LINER - LH	1	\$ 169.00		
34	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 89.00		
35	HEADLIGHT - LH	1	\$ 5,455.00	\$	4,364.00
36	HEADLIGHT LIFT CYLINDER - LH	1	\$ 142.00		
37	FRONT LOWER RADIATOR AIR GUIDE - LH	1	\$ 25.00	\$	19.44
38	FRONT UPPER RADIATOR AIR GUIDE - CENTER	1	\$ 12.00		
39	HEADLIGHT WASH WATER RESERVOIR	1	\$ 206.00		
40	HEADLIGHT HOSE	1	\$ 68.00		
SUB TOTAL SPARE PARTS		:	\$ 8,137.00	\$	7,752.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 6554 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 7,752.40
41	FRONT RADIATOR LOCK CARRIER MOUNT	1	\$ 727.00	\$ 581.60
42	RADIATOR COOLANT	6	\$ 142.00	\$ 113.28
43	FRONT NUMBER PLATE	S/N	\$ 60.00	\$ 60.00
44	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 19,808.00	\$ 8,507.28
TOTAL LABOUR CHARGES		:	\$ 10,002.00	3942
GRAND TOTAL		:	\$ 29,810.00	\$ 12,449.28

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED. REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



85 UBI ROAD 1, SINGAPORE 408689

TEL: 6386 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0364/2021/HR
DATE : 27-Apr-21
WIP : 24985

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. LIM THIAM POH
ADDRESS : 120A CANBERRA CRESCENT
#09-343
SINGAPORE 751120
TELEPHONE : HP +65 88384835
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800069387-01
VEHICLE NO : **SMA 6554 U**
MODEL CODE : A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 14/6/2018
ENGINE NO : CHZ 462599
CHASSIS NO : WAUZZZ8V8J1067407
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Apr-21
PLACE OF ACCIDENT : NEAR GOMBAK RISE



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 6554 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X.
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250 /
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	X ✓ 1200
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	500 1750.
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND HINGES.	\$ 3,000.00	550 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 10,002.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6341 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 6554 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Dehd</i>	1	\$ 1,987.00	✓	1589.60
2	FRONT BUMPER FIXING PARTS	1	\$ 187.00	+	
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 78.00	+	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 160.00	+	
5	FRONT BUMPER LOWER CLOSING ELEMENT - CENTER <i>new</i>	1	\$ 536.00	+	
6	FRONT BUMPER CLOSING ELEMENT - LH/ RH <i>3H Dehd</i>	2	\$ 594.00	✓ +	237.20
7	FRONT BUMPER TRIM - LH / RH <i>new</i>	1	\$ 326.00	+	
8	FRONT WHEEL HOUSING LINER ADAPTER - LH	1	\$ 38.00	+	
9	FRONT RADIATOR GRILLE <i>cracked</i>	1	\$ 1,406.00	✓	1124.80
10	FRONT RADIATOR CLOSING ELEMENT <i>cracked</i>	1	\$ 191.00	? ✓	152.40
11	AIR CONDITIONER STICKER <i>new</i>	1	\$ 8.00	✓	5.68
12	"CAUTION" STICKER	1	\$ 14.00	✓	10.78
13	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 188.00	+	
14	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 795.00	+	
15	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	1	\$ 189.00	✓	151.20
16	FRONT BUMPER REINFORCEMENT COVER <i>cracked</i>	1	\$ 122.00	✓	97.20
17	FRONT HIGH TONE HORN - LH <i>new</i>	1	\$ 200.00	+	
18	FRONT BONNET	1	\$ 3,134.00	+	
19	FRONT BONNET ATTACHMENT PARTS	1	\$ 165.00	+	
20	FRONT BONNET LID HINGE - LH / RH	2	\$ 124.00	+	
SUB TOTAL SPARE PARTS			\$ 10,442.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 6554 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BONNET CATCH HOOK	1	\$ 90.00	x
22	FRONT BONNET STRIKER - LH / RH	2	\$ 220.00	x
23	FRONT BONNET EDGE PROTECTION	1	\$ 28.00	x
24	FRONT BONNET CATCH HOOK	1	\$ 63.00	x
25	FRONT BONNET LID LOCK	2	\$ 427.00	x
26	FRONT BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	x
27	FRONT BONNET BOWDEN CABLE COVER - CENTER	1	\$ 10.00	+
28	FRONT FENDER - LH	1	\$ 851.00	+
29	POP RIVERT	5	\$ 17.00	+
30	FRONT FENDER ATTACHMENT PARTS - LH	1	\$ 72.00	+
31	FRONT FENDER BRACE	1	\$ 96.00	+
32	FRONT FENDER BRACKET - LH	1	\$ 39.00	+
33	FRONT WHEEL HOUSING LINER - LH	1	\$ 169.00	+
34	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 89.00	+
35	HEADLIGHT - LH	1	\$ 5,455.00	✓ + 4364
36	HEADLIGHT LIFT CYLINDER - LH	1	\$ 142.00	+
37	FRONT LOWER RADIATOR AIR GUIDE - LH	1	\$ 25.00	✓ + 19.44
38	FRONT UPPER RADIATOR AIR GUIDE - CENTER	1	\$ 12.00	+
39	HEADLIGHT WASH WATER RESERVOIR	1	\$ 206.00	+
40	HEADLIGHT HOSE	1	\$ 68.00	x
SUB TOTAL SPARE PARTS			\$ 8,137.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 6554 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	FRONT RADIATOR LOCK CARRIER MOUNT <i>3x cracked</i>	1	\$ 727.00	+ ✓ 581.60
42	RADIATOR COOLANT <i>3x new</i>	6	\$ 142.00	+ ✓ 113.28
43	FRONT NUMBER PLATE <i>Dented</i>	S/N	\$ 60.00	✓ 60
44	SUNDRIES <i>2x new.</i>		\$ 300.00	? X
TOTAL SPARE PARTS		:	\$	19,808.00
TOTAL LABOUR CHARGES		:	\$	10,002.00
GRAND TOTAL		:	\$	29,810.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6641 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Adrian
28/04/21

not Authorised, 03 Days

6 days
H.S.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT