

COMFORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305466253
Date : 03/05/21

FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHC 914C

Date of Accident : 28.04.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- YN7202T
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$3,450.00
Final Lumpsum Repair cost \$3,450.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : NAZ

Tel : 62148398

Date : 3/5/2021

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 29.04.2021

Time: 12:28:22

Page: 1

NTUC - LKS
LKK - Naz

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS: CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305466253
REGN NO : SHC 914C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I40
DATE OF REGN : 07.01.2016
DATE/TIME IN : 29.04.2021 09:05
ACCIDENT DATE : 28.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0572-A	BONNET	1	2,265.90	20.00	1,812.72	XR
0002 04-01-0103-0574-G	FRT FENDER LH	1	663.00	20.00	530.40	/ TN
0003 04-01-0103-2322-A	FRT BUMPER	1	1,052.20	20.00	841.76	/ DEF
0004 04-01-0103-0781-A	HEADLAMP LH	1	1,800.00	20.00	1,440.00	/ SCR
0005 04-01-0103-0600-G	WING MIRROR LH	1	670.00	20.00	536.00	XR

SUB-TOTAL : 5,160.88

JOB NATURE

0000 PB	PANEL BEATING	600.00	560
0001 SP	SPRAYPAINT CHARGE	1200.00	850
0002 17-01	CHECK ALL LIGHTING	40.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	60.00	40

SUB-TOTAL : 1,900.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 29.04.2021

Time: 12:28:22

Page: 2

NTUC - 45
LKK - NAZ

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305466253
REGN NO : SHC 914C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I40
DATE OF REGN : 07.01.2016
DATE/TIME IN : 29.04.2021 09:0
ACCIDENT DATE : 28.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 7,060.88

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

NAZ LKK
29/4/2021 1330
LLS
3 Days
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: