



Section A - Accident Details

Registration Number	SHB531D
Case Reference Number	TAX/04/21/2074
Registration Date	8/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TOK KAN HAI
Type of Accident	Head to Rear
Accident Date and Time	26/4/2021 2:50 PM
Accident Reported Date and Time	27/4/2021 9:06 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110716
Special Instruction to ARC, if any	TP /REAR \PORTION/ DROVE IN
Prepared Date and Time	27/4/2021 11:10 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$2,232.00	\$400.00
Total Spare Part Cost	\$6,098.16	\$849.85
Total Other Cost	\$805.32	\$346.88
TOTAL COST	\$9,811.48	\$1,996.73
Lump Sum Total	\$9,800.00	\$2,000.00 (L/S)
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Ang Bang Kien	GUO QIANG (LKK) / EQ
ARC / Surveyor Sign Off Date	30/04/2021 11:13 AM	30/04/2021 10:15 AM
Signature		
Remarks	Total number of repair days = 4 days. SUP = 0 day.	lump sum repair / after paint photo /

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2105-0162	Invoice Number	
Quotation Date	14.05.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$676.00	\$400.00
Total Labour	\$676.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO REPSRAY REAR DOOR LH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$2,232.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$445.32	\$296.88
Total Other Costs	\$805.32	\$346.88

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check
		89997-30070	ANTENNA,ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given

